

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21010166/UPA3Q2**Date:** 11/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993682
Claimant Vehicle No :	FZ2045A	Insured Vehicle No :	GBK5333A
Date of Loss:	26/09/2021	Nature of Claim:	TP
		Claim No:	8536036663SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FZ2045A	Engine No:	J507E061713
Make & Model:	YAMAHA FZ6-S, 600cc (M)	Chassis No:	JYARJ071000035866
Reg. Date:	09/05/2005 (Man. Year: 2005)	Odometer:	36824 km
Colour:	Blue/Silver		
Engine Capacity:	600 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70Z R17	Rear Tyre Size:	180/55Z R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,618.00	3,196.50	3,421.50	51.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,109.00	870.00	239.00	21.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,727.00	4,066.50	3,660.50	47.37
Approved Total (Overridden) (S\$)		3,250.00		
(S\$)	7,727.00	3,250.00	4,477.00	57.94
+ GST 7.00/7.00% (S\$)	540.89	227.50	313.39	57.94
Nett Amount (S\$)	8,267.89	3,477.50	4,790.39	57.94
+ Loss of Use (4.0 x S\$20.00/day) (S\$)		80.00		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		3,617.50		
Global Sum Settlement (S\$)		3,610.00		

INSPECTION

Date of Assignment:	01/10/2021		
Date Inspected:	01/10/2021	Inspected At:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4 Singapore 539410
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

(FOR MANDATE ONLY)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ALIGNMENT BODY REAR	Not Necessary	525.00 F	*- FL
2	1		*BALANCER HANDLE (MOTOVATION)	Scratched	143.00 F	*143.00 FL
3	2		*BEARING SWING ARM	Not Necessary	66.00 F	*- FL
4	1		*BELLY PAN (PUIG)	Cut	510.00 F	*510.00 FL
5	1		*BODY FRONT UPPER 1	Cracked	191.00 F	*191.00 FL
6	1		*BOX REAR (KAPPA) KGR52	Damaged	600.00 F	*600.00 FL
7	1		*BRACKET 6	Necessary	41.00 F	*41.00 FL
8	1		*BRACKET BOX REAR (MONORACK)	Bent	330.00 F	*330.00 FL
9	1		*CLAMP	Necessary	4.50 F	*4.50 FL
10	1		*CLAMP	Necessary	1.50 F	*1.50 FL
11	1		*CLAMP WIRE	Necessary	8.00 F	*8.00 FL
12	1		*COVER REAR FENDER	Warped	73.00 F	*73.00 FL
13	1		*COVER REAR FENDER 1	Deformed	9.00 F	*9.00 FL
14	1		*DAMPER	Not Necessary	1.50 F	*- FL
15	1		*DAMPER 1	Not Necessary	4.50 F	*- FL
16	2		*DAMPER 2	Not Necessary	3.00 F	*- FL
17	2		*EMBLEM 1	Necessary	18.00 F	*18.00 FL
18	1		*FOOTREST FRONT RH	Cut	52.00 F	*52.00 FL
19	1		*FOOTREST REAR 2	Cut	27.00 F	*27.00 FL
20	1		*GUIDE MUDGUARD	Not Necessary	6.00 F	*- FL
21	1		*HANDLE BAR	Bent	73.00 F	*73.00 FL
22	1		*HANDLE SEAT	Repair	380.00 F	*- FL
23	1		*LAMP SIGNAL FRONT RH	Cut	111.00 F	*111.00 FL
24	1		*LEVER BRAKE	Scratched	112.00 F	*112.00 FL
25	1		*LIGHT LICENSE PLATE	Broken	95.00 F	*95.00 FL
26	1		*MUDFLAP REAR	Deformed	45.00 F	*45.00 FL
27	1		*MUFFLER (AKRAPOVIC) ASSY (LOCAL REPAIR)	Dented	2,052.00 FS	*150.00 FS
28	1		*PEDAL BRAKE	Cut	95.00 F	*95.00 FL
29	2		*PLUG	Not Necessary	10.00 F	*- FL
30	1		*PULLER CHAIN 2	Not Necessary	20.00 F	*- FL
31	1		*REAR FLASHER LIGHT ASSY 1	Cracked	63.00 F	*63.00 FL
32	1		*REAR FLASHER LIGHT ASSY 2	Damaged	63.00 F	*63.00 FL
33	1		*REAR VIEW MIRROR ASSY (RIGHT)	Cut	111.00 F	*111.00 FL
34	1		*REFLECTOR REAR (RED)	Broken	18.00 F	*18.00 FL
35	1		*REPAIR ON SWINGARM	Not Necessary	60.00 F	*- FL
36	2		*RIVET	Not Necessary	3.00 F	*- FL
37	1		*RUBBER FOOTREST FRONT	Cut	22.00 F	*22.00 FL
38	1		*SEAL	Necessary	1.50 F	*1.50 FL
39	1		*SEAL 1	Necessary	4.50 F	*4.50 FL
40	1		*SEAL 2	Not Necessary	17.00 F	*- FL
41	1		*SHAFT SWINGARM	Not Necessary	69.00 F	*- FL
42	1		*SIDE COVER ASSY 1	Cut	48.00 F	*48.00 FL
43	1		*SIDE COVER ASSY 2	Cut	48.00 F	*48.00 FL
44	1		*SLIDER FRAME (MOTOVATION)	Cut	126.00 F	*126.00 FL
45	2		*STAY FLASHER 1	Necessary	3.00 F	*3.00 FL
46	2		*TRIM	Not Necessary	16.00 F	*- FL
47	2		*WASHER THRUST SWINGAR,	Necessary	38.00 F	*38.00 FL
48	1		*WINDSHIELD (PUIG)	Cracked	300.00 F	*300.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,618.00	3,535.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	338.50
Total Parts (\$\$)	6,618.00	3,196.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	630.00	480.00
2	SPRAY PAINT ON HANDLE SEAT	New	84.00	80.00
3	SPRAY PAINT ON BODY FRONT UPPER 1	New	165.00	150.00
4	SPRAY PAINT ON SIDE COVER ASSY 1	New	90.00	80.00
5	SPRAY PAINT ON SIDE COVER ASSY 2	New	90.00	80.00
6	SPRAY PAINT WINDSHIELD	New	50.00	0.00
Gross Labour Cost (\$)			1,109.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >