9/15/22, 2:20 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21010167/GEA3Q2

15/09/2022 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 099993686 **Claimant Vehicle**

SHC8511D Insured Vehicle No: SKT6920U No:

Date of Loss: 30/09/2021 Nature of Claim: TP Claim No: 2770152326SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC8511D

Make & Model: HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A) G4LEKU421503 Engine No:

Reg. Date: 29/01/2021 (Man. Year: 2019) Chassis No: KMHC851CVLU192842

Colour: Odometer: 66819 km Blue

Engine Capacity: 1580 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Rear Left Side: West Lake 6 mm West Lake 6 mm Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,614.68	1,900.40	714.28	27.32
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,640.00	990.00	650.00	39.63
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	4,254.68	2,890.40	1,364.28	32.07
	+ GST 7.00/7.00% (S\$)	297.83	202.33	95.50	32.07
	Nett Amount (S\$)	4,552.51	3,092.73	1,459.78	32.07
	+ Loss of Use (3.0 x	S\$50.00/day) (S\$)	150.00		
	+ Car Rental (3.0 x S	\$125.19/day) (S\$)	375.57		
	+ Do	c/Search Fee (S\$)	7.49		
		Nett Liability (S\$)	3,625.79		
	Global Su	m Settlement (S\$)	3,620.00		

INSPECTION

Date of Assignment: 01/10/2021

ComfortDelGro Engineering Pte Ltd (Loyang) Date Inspected:

01/10/2021 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 4.0 days

XING GUO QIANG Adjuster: Manager: Asher Sng Rong Yi

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WING MIRROR LH	Cut	1,391.70 FL	*1,391.70 FL
2	1		*FRONT FENDER LH	Buckled	588.80 FL	*588.80 FL
3	1		*FRONT FENDE BLUE-DRIVE LH	Necessary	26.60 FL	*26.60 FL
4	1		*FRONT BUMPER	Repair	430.90 FL	*- FL
5	1		*FRONT BUMPER UPPER MOULDING	Not Necessary	368.50 FL	*- FL
6	1		*REAR BUMPER GRILLE LH	Not Necessary	93.45 FL	*- FL
7	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
8	1		*FRONT WHEEL CAP LH	Scratched	346.40 FL	*346.40 FL
F=Fra	anchise	part. L=ListIte	mDisc.	_		
				Sub Total (S\$)	3,268.35	2,375.50
			- List Item Discount on	L Items 20.00/20.00% (S\$)	653.67	475.10
				Total Parts (S\$)	2,614.68	1,900.40
			Report was unsubmitted d	uring this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	PANEL BEATING	New	800.00	350.00
2	SPRAY PAINTING	New	800.00	600.00
3	TUFF KOTE	New	40.00	40.00
		Gross Labour Cost (S\$)	1,640.00	990.00
		Report was unsubmitted during this print-out.		

< END OF ESTIMATES >