

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CS/CTI21010170/BQCQ2

Date:

15/11/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00009252101
Claimant Vehicle No :	SJS2667U	Insured Vehicle No :	SML9155K
Date of Loss:	29/09/2021	Nature of Claim:	TP
			Claim No: SNM21D205585/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS2667U		
Make & Model:	HYUNDAI HD AVANTE 1.6 A (BI-FUEL), 1.6 (A)	Engine No:	G4FC9U653628
Reg. Date:	07/08/2009 (Man. Year: 2009)	Chassis No:	KMH DU41BR9U759143
Colour:	Blue	Odometer:	307918 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	ATREZZO 5 mm	Rear Left Side:	APLUS 5 mm
Front Right Side:	ATREZZO 5 mm	Rear Right Side:	APLUS 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,835.12	4,105.57	4,729.55	53.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,050.00	1,960.00	2,090.00	51.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,885.12	6,065.57	6,819.55	52.93
Approved Total (Overridden) (S\$)		4,850.00		

(S\$)	12,885.12	4,850.00	8,035.12	62.36
+ GST 7.00/7.00% (S\$)	901.96	339.50	562.46	62.36
Nett Amount (S\$)	13,787.08	5,189.50	8,597.58	62.36

INSPECTION

Date of Assignment: 03/10/2021

Date Inspected: 04/10/2021

Estimated Period of Repair: 7.0 days

 Inspected At: 160 SIN MING DR #01-14 SIN MING AUTO CITY
 Repairer: Team Autopro Pte Ltd (Sin Ming)
Adjuster: Lim Teow Guan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Nov 2021)
Parts:	143	HYUNDAI HD AVANTE 1.6 A (BI-FUEL) 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS2667U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	758.30 FL	*758.30 FL
2	1		*BOOTLID LOGO	Necessary	88.00 FL	*56.00 FL
3	1		*BOOTLID EMBLEM AVANTE	Necessary	84.30 FL	*61.20 FL
4	1		*BOOTLID EMBLEM S	Necessary	74.20 FL	*32.00 FL
5	1		*BOOTLID OUTER GARNISH	Cut	310.00 FL	*136.80 FL
6	2		*BOOTLID LAMP	Broken	916.00 FL	*549.80 FL
7	1		*BOOTLID LOCK	Jammed	268.00 FL	*158.40 FL
8	1		*BONNET STRIKER	Not Damaged	58.00 FL	*- FL
9	1		*BOOTLID WEATHERSTRIP	Torn	198.60 FL	*112.36 FL
10	1		*BOOTLID INNER TRIM BOARD	Not Damaged	189.00 FL	*- FL
11	1		*BOOTLID CHECK	Not Damaged	85.30 FL	*- FL
12	1		*REAR BUMPER	Broken	685.90 FL	*484.00 FL
13	2		*REAR BUMPER LOWER BRACKET	No such part	157.00 FL	*- FL
14	2		*REAR BUMPER SIDE RETAINER	Necessary	197.40 FL	*97.80 FL
15	1		*REAR BUMPER REINFORCEMENT	Broken	389.10 FL	*282.80 FL
16	2		*REAR BUMPER REINFORCEMENT BRACKET	Dented	448.00 FL	*129.60 FL
17	1		*REAR BUMPER INNER SPONGE	Broken	212.50 FL	*108.00 FL
18	1		*REAR END PANEL	Dented	672.00 FL	*485.10 FL
19	1		*REAR END PANEL TOP GARNISH	Broken	98.00 FL	*85.60 FL
20	1		*SPARE TYRE PANEL	Not Damaged	584.20 FL	*- FL
21	1		*SPARE TYRE TOP BOARD	Not Damaged	320.00 FL	*- FL
22	1		*REAR FENDER LH	Repair	852.30 FL	*- FL
23	2		*REAR FENDER INNER TRIM BOARD	Broken	518.60 FL	*416.00 FL
24	2		*TAIL LAMP	Broken	979.20 FL	*653.20 FL
25	1		*BOOTLID SEALANT	Necessary	100.00 FS	*30.00 FS
26	1		*BOOTLID OUTER GARNISH CLIPS	No such part	50.00 FS	*- FS
27	2		*BOOTLID LAMP CLIPS	No such part	100.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	2		*BOOTLID LAMP SEAL	Necessary	120.00 FS	*40.00 FS
29	1		*BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
30	1		*REAR NUMBER PLATE W/CASING	Not Damaged	80.00 FS	*- FS
31	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
32	2		*REAR BUMPER REVERSE SENSORS	Scratched	500.00 FS	*200.00 FS
33	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
34	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
35	2		*REAR FENDER INNER TRIM CLIPS	Necessary	100.00 FS	*30.00 FS
36	2		*TAIL LAMP CLIPS	No such part	100.00 FS	*- FS
37	2		*TAIL LAMP SEAL	Necessary	120.00 FS	*40.00 FS
					Sub Total (S\$)	10,663.90
					- List Item Discount on L Items 20.00/20.00% (S\$)	1,828.78
					Total Parts (S\$)	8,835.12
						4,105.57

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R BOOTLID COMPONENT	New	150.00	80.00
2	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
3	UPHOLSTERY	New	300.00	0.00
4	CHECK WIRING	New	100.00	20.00
5	PANEL BEATING	New	1,600.00	1,000.00
6	RUST PROOFING	New	200.00	0.00
7	SPRAY PAINTING	New	1,600.00	800.00
Gross Labour Cost (S\$)			4,050.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >