

Our Job Ref No 305488935Date : 05/10/21ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**To : LKK

Fax :

Attn : GUO QIANG: SHC1105PDOA: 30.09.21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: ECICS --- SJT5625R

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%\$2,650.00**Final Lumpsum Repair cost**3. Estimated normal period for repairs: 3 working days4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : Name : JUMANITel : 6214 8315Fax : 65468156

Signature : _____

Name : GUO QIANG

Date : _____

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	7.49 / 2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

VEHICLE NO. : SHC1105P

TYPE OF CASE : ECICS

JOB CARD NO. 305488935

SURVEY BY : LKK-GUO

ACC. DATE 30.09.21

DATE :

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

DESCRIPTION	QTY	ESTIMATE	REMARKS
REVERSE SENSOR ✓ DM		\$135.70	NET
CHECK ITEM			
REAR BUMPER REINFORCEMENT		\$318.80	LIST
REAR BUMPER TOW COVER		\$82.70	LIST
LABOUR			
TOTAL:		\$537.20	JUMANI