



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFA 8238C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	BUCKLED / CUT	495.00	495.00
1	FRONT BUMPER SIDE RETAINER	DISTORTED	55.00	55.00
20	FRONT BUMPER CLIP	NECESSARY	100.00	100.00
1	FRONT FENDER LH	BENT	747.00	747.00
10	FRONT FENDER COWLING CLIP	NECESSARY	50.00	50.00
1	HEADLAMP LH	CRACKED	1,150.00	1,150.00
	LESS 25% DISCOUNT		-649.25	-649.25
			1,947.75	1,947.75
1	FRONT LH ALLOY RIM (SN)	DENTED	1,400.00	250.00
	LESS 25% DISCOUNT		-350.00	-
			1,050.00	250.00
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING AND REFOCUS HEADLAMP.		30.00	20.00
	TO WHEEL ALIGNMENT.		80.00	60.00
	TO REMOVE, REFIT AND BALANCING FRONT LH WHEEL.		30.00	20.00
	TO DISMANTLE AND INSTALL DAMAGE PARTS, TO KNOCK, ALIGN AND REPAIR FRONT AFFECTED AREA AND TO REFIT LISTED PARTS BACK SAME.		700.00	400.00
	TO SPRAY FRONT FENDER AND FRONT BUMPER.		600.00	400.00
			1,440.00	900.00
	<b>GRAND TOTAL</b>		<b>4,437.75</b>	<b>3,097.75</b>
	<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)</b>			<b>3,097.75</b>

Report Ref No. CS/GAI21010173/Kvf3e2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.