

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21010180/EVF3E2

Date: 08/10/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070139490
Claimant Vehicle No : GBG4868B **Insured Vehicle No :** GBG7356S
Date of Loss: 29/09/2021 Nature of Claim: TP Claim No: 4514735092SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG4868B**
Make & Model: MITSUBISHI CANTER, 3.0 D FEA01BR2SDEB (CBU) (M) Engine No: 4P10C61631
Reg. Date: 24/08/2017 (Man. Year: 2017) Chassis No: FEA01BA20643
Colour: White Odometer: 95878 km
Engine Capacity: 2998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm
Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 03/10/2021
Date Inspected: 04/10/2021 Inspected At: Block K No. 2 Pandan Loop
Estimated Period of Repair: 4.0 days Repairer: Eng Hup Seng Motor

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$50,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Dented	0.00 F	*- F
2	1		*FRT BUMPER SIDE COVER	Dented	0.00 F	*- F
3	1		*FRT BUMPER BRACKET	* Check	0.00 F	*- F
4	1		*FRT GRILLE	Broken	0.00 F	*- F
5	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
6	1		*FRT CORNER PANEL	Broken	0.00 F	*- F
7	1		*FRT SIGNAL LAMP RH	Broken	0.00 F	*- F
8	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F
9	1		*FRT RH SIDE LAMP	Broken	0.00 F	*- F
10	1		*FRT SIDE MIRROR (BIG)	Broken	0.00 F	*- F
11	1		*FRT RH DOOR HINGE	Bent	0.00 F	*- F
12	1		*FRT RH DOOR GLASS GARNISH	Cut	0.00 F	*- F
13	1		*FRT RH DOOR	Dented	0.00 F	*- F
14	1		*FRT RH DOOR GLASS	Cut	0.00 F	*- F
15	1		*FRT STEP PANEL TOP GARNISH	Cut	0.00 F	*- F
F=Franchise part.						
					Total Parts (S\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >