

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21010181/GTF3E2

Date: 05/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100460884
Claimant Vehicle No :	FBP3023G	Insured Vehicle No :	SLD2828C
Date of Loss:	30/09/2021	Nature of Claim:	TP
		Claim No:	2943639176SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBP3023G	Engine No:	KC27E2221562
Make & Model:	HONDA FS150F, 149cc	Chassis No:	PMKKC27A0KB207921
Reg. Date:	11/03/2019 (Man. Year: 2019)	Odometer:	77560 km
Colour:	Orange		
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	90/80-17	Rear Tyre Size:	120/70-17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	04/10/2021		
Date Inspected:	04/10/2021	Inspected At:	Speedy Motor Cycle Service Centre (HQ) 10 ANG MO KIO IND PARK 2A #05-21 Singapore 568047
Estimated Period of Repair:	3.0 days		

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$7,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
2	1		*FRONT HEADLAMP	Cut	0.00 F	*- F
3	1		*FRONT WING MIRROR LH	Bent	0.00 F	*- F
4	1		*FRONT LH SIGNAL LAMP	Cracked	0.00 F	*- F
5	1		*FRONT RH SIGNAL LAMP	Cracked	0.00 F	*- F
6	1		*ERP UNIT CASE	Cut	0.00 F	*- F
7	1		*HANDLE BAR	Bent	0.00 F	*- F
8	1		*HANDLE BAR GRIP	Necessary	0.00 F	*- F
9	1		*HANDLE BAR BALANCER RH	Cut	0.00 F	*- F
10	1		*CLUTCH LEVER	Cut	0.00 F	*- F
11	1		*HAND BRAKE LEVER	Cut	0.00 F	*- F
12	1		*REAR FAIRING RH	Cut	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >