

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010183/BVCN2**Date:** 06/01/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00095352000

Claimant Vehicle No : SJG8030E **Insured Vehicle No :** GY9680M

Date of Loss: 22/09/2021 Nature of Claim: TP Claim No: SNM21D205410/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJG8030E**

Make & Model: HONDA CIVIC, 1.8 (A) Engine No: R18A13038628

Reg. Date: 16/07/2008 (Man. Year: 2008) Chassis No: JHMFD16308S217356

Colour: Red Odometer: 194328 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17

Front Left Side: Michelin 4 mm Rear Left Side: Goodyear 4 mm

Front Right Side: Michelin 4 mm Rear Right Side: Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,867.81	3,499.70	6,368.11	64.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,040.00	800.00	2,240.00	73.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,907.81	4,299.70	8,608.11	66.69
Approved Total (Overridden) (S\$)		3,450.00		
(S\$)	12,907.81	3,450.00	9,457.81	73.27
+ GST 7.00/7.00% (S\$)	903.55	241.50	662.05	73.27
Nett Amount (S\$)	13,811.36	3,691.50	10,119.86	73.27

INSPECTION

Date of Assignment: 04/10/2021

Date Inspected: 04/10/2021 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: Lim Teow Guan**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jan 2022)
Parts:	143	HONDA CIVIC 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJG8030E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT BONNET STOPPER	Not Damaged	50.00 FL	*- FL
2	1		*FRONT BONNET LOCK	Not Damaged	226.92 FL	*- FL
3	1		*FRONT SUPPORT PANEL	Not Damaged	757.20 FL	*- FL
4	1		*FRONT REINFORCEMENT	Not Damaged	447.00 FL	*- FL
5	1		*FRONT REINFORCEMENT ARM BRACKET R	Not Damaged	185.00 FL	*- FL
6	1		*FRONT REINFORCEMENT ARM BRACKET L	Not Damaged	185.00 FL	*- FL
7	1		*FRONT HEADLAMP RH	Broken	950.00 FL	*912.10 FL
8	1		*FRONT HEADLAMP LH	Broken	950.00 FL	*912.10 FL
9	1		*FRONT HEADLAMP LOWER BRACKET R	Bent	101.00 FL	*101.00 FL
10	1		*FRONT HEADLAMP LOWER BRACKET L	Bent	101.00 FL	*101.00 FL
11	1		*FRONT BUMPER	Broken	874.60 FL	*638.00 FL
12	2		*FRONT BUMPER SIDE RETAINER	Necessary	120.00 FL	*90.00 FL
13	1		*FRONT BUMPER NUMBER PLATE GARNISH	Not Damaged	85.00 FL	*- FL
14	1		*FRONT BUMPER GRILLE	Broken	454.20 FL	*352.70 FL
15	1		*FRONT BUMPER GRILLE CHROME	Broken	331.20 FL	*151.10 FL
16	1		*FRONT BUMPER LOGO	Not Necessary	99.00 FL	*- FL
17	1		*FRONT BUMPER LOWER GRILLE	Not Damaged	320.00 FL	*- FL
18	1		*FRONT FOGLAMP L	Not Damaged	220.00 FL	*- FL
19	1		*FRONT FOGLAMP R	Not Damaged	220.00 FL	*- FL
20	1		*FRONT FOGLAMP GARNISH R	Not Damaged	86.00 FL	*- FL
21	1		*FRONT FOGLAMP GARNISH L	Not Damaged	86.00 FL	*- FL
22	1		*FRONT AIR RESONATOR BOX	Not Damaged	480.12 FL	*- FL
23	1		*FRONT SUPPORT PANEL COVER	Not Damaged	168.17 FL	*- FL
24	1		*AIRCON CONDENSER	Not Damaged	1,052.70 FL	*- FL
25	1		*RADIATOR	Not Damaged	1,300.30 FL	*- FL
26	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
27	1		*FRONT BUMPER GRILLE CLIP	Necessary	40.00 FS	*20.00 FS
28	1		*FRONT BUMPER LOWER GRILLE CLIP	Necessary	40.00 FS	*20.00 FS
29	1		*BONNET	Cracked	1,800.00 FS	*986.20 FS
30	1		*FRONT BUMPER LOWER SPOILER	Not Damaged	500.00 FS	*- FS
31	1		*FRONT NUMBER PLATE	Not Damaged	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,330.41	4,314.20
- List Item Discount on L Items 25.00/25.00% (\$)	2,462.60	814.50
Total Parts (\$)	9,867.81	3,499.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING TO ALL AFFECTED AREAS	New	1,200.00	400.00
2	REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK,JACK,CUT,WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,000.00	400.00
3	CHECK WIRING SYSTEM AND LIGHT	New	100.00	0.00
4	ANTI RUST TREATMENT	New	120.00	0.00
5	CHECK WATER LEAKING	New	120.00	0.00
6	REMOVE/REFIX/REPLACE RADIATOR,RADIATOR FAN MOTOR,AIRCON CONDENSER (PIPING,HOSE,TOP UP GAS,REFILL COOLANT ETC)	New	200.00	0.00
7	COMPUTER DIAGNOSTIC AFTER REPAIR	New	300.00	0.00
Gross Labour Cost (\$\$)			3,040.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >