

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010190/KVCN2**Date:** 18/11/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00115542100

Claimant Vehicle No : SML6308G **Insured Vehicle No :** GBG1070E

Date of Loss: 19/09/2021 Nature of Claim: TP Claim No: SNM21D205331/C04/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML6308G**

Make & Model: MERCEDES-BENZ C180, 1.8 (A) Engine No: 27491031665902

Reg. Date: 29/05/2019 (Man. Year: 2018) Chassis No: WDD2050402R470129

Colour: Metallic Grey Odometer: 68114 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50R17 Rear Tyre Size: 225/50R17

Front Left Side: Pirelli 9 mm Rear Left Side: Pirelli 9 mm

Front Right Side: Pirelli 9 mm Rear Right Side: Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,544.60	10,782.00	3,762.60	25.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,420.00	2,510.00	1,910.00	43.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,964.60	13,292.00	5,672.60	29.91
+ GST 7.00/7.00% (S\$)	1,327.52	930.44	397.08	29.91
Nett Amount (S\$)	20,292.12	14,222.44	6,069.68	29.91

INSPECTION

Date of Assignment: 05/10/2021

Date Inspected: 04/10/2021 Inspected At: Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 9.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Nov 2021)
Parts:	M1-COUPE	MERCEDES-BENZ C180 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML6308G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BOOTLID	Bent	2,405.00 FN	*2,405.00 FN
2	1	*BOOTLID CENTRE CHROME	Dented	147.00 FN	*147.00 FN
3	1	*BOOTLID WEATHERSTRIP	Distorted	220.00 FN	*220.00 FN
4	1	*BOOTLID CENTRE LOGO	Necessary	54.00 FN	*54.00 FN
5	1	*BOOTLID C180 EMBLEM	Necessary	109.00 FN	*109.00 FN
6	1	*BOOTLID 9G-TRONIC EMBLEM	Necessary	128.00 FN	*128.00 FN
7	1	*REAR END PANEL	Bent	1,578.00 FN	*1,578.00 FN
8	1	*TAILLAMP PANEL-LH	Bent	180.00 FN	*180.00 FN
9	1	*TAILLAMP ASSY-LH	Broken	775.00 FN	*775.00 FN
10	1	*REAR FENDER-LH	Bent	2,560.00 FN	*2,556.00 FN
11	1	*REAR FENDER GARNISH-LH	Dented	208.00 FN	*208.00 FN
12	1	*REAR FENDER INNER TRIM-LH	Deformed	325.00 FN	*325.00 FN
13	1	*REAR FENDER INNER TRIM COVER-LH	Dented	88.00 FN	*88.00 FN
14	1	*REAR BUMPER	Bent	1,805.00 FN	*1,805.00 FN
15	1	*REAR BUMPER REINFORCEMENT	Repair	740.00 FN	*- FN
16	1	*REAR BUMPER SIDE RETAINER-LH	Cracked	65.00 FN	*65.00 FN
17	1	*REAR BUMPER LOWER SPOILER	Cracked	292.00 FN	*292.00 FN
18	1	*REAR BUMPER LOWER CHROME	Dented	321.00 FN	*321.00 FN
19	1	*REAR BUMPER TOW COVER	Serviceable	59.00 FN	*- FN
20	1	*REAR BUMPER SENSOR	Shorted	195.00 FN	*195.00 FN
21	4	*REAR BUMPER SENSOR SEALS	Necessary	48.00 FN	*48.00 FN
22	1	*REAR BUMPER CENTRE INNER FRAME	Serviceable	105.00 FN	*- FN
23	1	*REAR BUMPER BRACKET-LH	Cracked	65.00 FN	*65.00 FN
24	1	*REAR FENDER INNER SHIELD-LH	Serviceable	208.00 FN	*- FN
25	1	*REAR DOOR-RH-LH	Repair	2,455.00 FN	*- FN
26	1	*REAR DOOR WEATHERSTRIP-LH	Serviceable	328.00 FN	*- FN
27	20	*REAR DOOR TRIMBOARD RIVETS-LH	Not Necessary	180.00 FN	*- FN
28	1	*REAR BUMPER CLIPS (15 Pcs)	Necessary	121.50 FS	*50.00 FS
29	1	*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
30	1	*TAILLAMP LOWER BRACKET-LH	Distorted	95.00 FN	*95.00 FN
31	1	*REAR FENDER CONTROL MODULE MOUNT BRACKET-LH	Cracked	169.00 FN	*169.00 FN
32	1	*REAR FENDER AIR GRILLE-LH	Dented	52.00 FN	*52.00 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	16,140.50	11,970.00
- Nett Item Discount on N Items 10.00/10.00% (S\$)	1,595.90	1,188.00
Total Parts (S\$)	14,544.60	10,782.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
2	TO REMOVE AND REFIT REAR INTERIOR GARNISH AND TRIMBOARD TO FACILITATES THE REPAIRS	New	180.00	120.00
3	TO TRANSFER LH REAR DAMAGED DOOR INTERIOR MECHANISM AND GLASS TO NEW DOOR	New	150.00	0.00
4	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	100.00	60.00
5	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
6	TO PANEL BEAT AND STRAIGHTEN LH REAR FENDER INNER PANEL,LH REAR CHASSIS FRAME.TO CUT AND WELD REAR END PANEL,LH REAR TAILLAMP PANEL,LH REAR FENDER,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY,TO REFIT AND ADJUST THE SAME	New	1,800.00	1,200.00
7	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,800.00	900.00
8	TO SPRAY RUST-PROOFING ON REPLACED AND REPAIRED PANELS	New	160.00	90.00
Gross Labour Cost (\$\$)			4,420.00	2,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >