7/19/22, 3:17 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III21010193/UEA3Q2

**Date:** 19/07/2022

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MCV0004785

Claimant Vehicle SGQ4810E Insured Vehicle No: GBH5775Z

No:

Date of Loss: 01/10/2021 Nature of Claim: TP Claim No: MCV2021D0004341

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SGQ4810E

 Make & Model:
 HONDA STREAM, 1.8 (A)
 Engine No:
 R18A1715180

 Reg. Date:
 17/01/2007 (Man. Year: 2006)
 Chassis No:
 RN61014024

 Colour:
 Blue
 Odometer:
 179506 km

Engine Capacity: 1799 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 225/45Z R17 Rear Tyre Size: 225/45Z R17
Front Left Side: KAPSEN 6 mm Rear Left Side: KAPSEN 6 mm
Front Right Side: KAPSEN 6 mm
KAPSEN 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS      |                                   | Repairer's          | Adjuster's | Difference | Diff % |
|---------------------|-----------------------------------|---------------------|------------|------------|--------|
| Parts               |                                   | 3,969.70            | 1,775.52   | 2,194.18   | 55.27  |
| Miscellaneous Items |                                   | 0.00                | 0.00       | 0.00       |        |
| Labour              |                                   | 1,910.00            | 1,250.00   | 660.00     | 34.55  |
| Paintwork Labour    |                                   | 0.00                | 0.00       | 0.00       |        |
| Towing              |                                   | 0.00                | 0.00       | 0.00       |        |
|                     | Calculated Gross Total (S\$)      | 5,879.70            | 3,025.52   | 2,854.18   | 48.54  |
|                     | Approved Total (Overridden) (S\$) |                     | 2,000.00   |            |        |
|                     | Nett Amount (S\$)                 | 5,879.70            | 2,000.00   | 3,879.70   | 65.98  |
|                     | + Car Rental (3.0 x S\$1          | 120.00/day) (S\$)   | 360.00     |            |        |
|                     |                                   | (S\$)               | 2,360.00   |            |        |
|                     | Liable Amou                       | nt (50.00%) (S\$)   | 1,180.00   |            |        |
|                     | + Doc/s                           | Search Fee (S\$)    | 7.45       |            |        |
|                     | No                                | ett Liability (S\$) | 1,187.45   |            |        |
|                     | Global Sum                        | Settlement (S\$)    | 1,200.00   |            |        |

**INSPECTION** 

Date of Assignment: 04/10/2021

Choo Motor Spray Painter (HQ)

Date Inspected: 04/10/2021 Inspected At: 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki

Bukit

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

7/19/22, 3:17 PM

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Nov 2021)

Parts: M1-MPV HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGQ4810E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

| No.   | Qty     | Part No.        | Particulars                              | Condition            | Repairer's | Amount     |
|-------|---------|-----------------|--|----------------------|------------|------------|
| 1     | 1       |                 | *BONNET                                  | Repair               | 745.20 F   | *- FL      |
| 2     | 1       |                 | *FRONT BUMPER                            | Distorted            | 665.40 F   | *665.40 FL |
| 3     | 1       |                 | *FRONT BUMPER SIDE RETAINER N/S          | Cracked              | 28.50 F    | *28.50 FL  |
| 4     | 1       |                 | *FRONT BUMPER BEAM                       | Not Necessary        | 245.20 F   | *- FL      |
| 5     | 1       |                 | *SET FRONT BUMPER CLIPS                  | Necessary            | 39.00 F    | *39.00 FL  |
| 6     | 1       |                 | *HEADLAMP N/S                            | Broken               | 866.20 F   | *866.20 FL |
| 7     | 1       |                 | *HEADLAMP LOWER BRACKET N/S              | Not Necessary        | 69.50 F    | *- FL      |
| 8     | 1       |                 | *FRONT FENDER N/S                        | Distorted            | 620.30 F   | *620.30 FL |
| 9     | 1       |                 | *FRONT FENDER INNER SHIELD N/S           | Not Necessary        | 188.60 F   | *- FL      |
| 10    | 1       |                 | *SET FRONT FENDER INNER SHIELD CLIPS N/S | Not Necessary        | 35.00 F    | *- FL      |
| 11    | 1       |                 | *FRONT SUPPORT PANEL                     | Repair               | 466.80 F   | *- FL      |
| F=Fra | anchise | part. L=ListIte | emDisc.                                  | -                    |            |            |
|       |         |                 |  | Sub Total (S\$)      | 3,969.70   | 2,219.40   |
|       |         |                 | - List Item Discount on L Ite            | ms 0.00/20.00% (S\$) | 0.00       | 443.88     |
|       |         |                 |  | Total Parts (S\$)    | 3,969.70   | 1,775.52   |

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

| No  | Particulars                               | Lab.Type                     | Repairer's | Amount   |
|-----|---|------------------------------|------------|----------|
| Lab | our Items                                 |                              |            |          |
| 1   | TO CHECK WIRING                           | New                          | 50.00      | 20.00    |
| 2   | TO SPRAY RUST PROOFING                    | New                          | 80.00      | 30.00    |
| 3   | TO CONDUCT WHEEL ALIGNMENT                | New                          | 120.00     | 0.00     |
| 4   | LABOUR FOR PANEL BEATING & REPLACED PARTS | New                          | 680.00     | 500.00   |
| 5   | TO PUTTY & SPRAY PAINTING                 | New                          | 980.00     | 700.00   |
|     |   | Gross Labour Cost (S\$)      | 1,910.00   | 1,250.00 |
|     | Report was unsubm                         | itted during this print-out. |            |          |

< END OF ESTIMATES >