

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010194/UQC2**Date:** 20/10/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00070042100	
Claimant Vehicle No :	FBQ7277J	Insured Vehicle No :	SMZ370R	
Date of Loss:	22/09/2021	Nature of Claim:	TP	Claim No: SNM21D205614/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBQ7277J		Engine No:	SJ301000165
Make & Model:	KYMCO SUPER JOCKEY 150I, 149cc		Chassis No:	RFBSJ30GAK1000144
Reg. Date:	03/12/2019 (Man. Year: 2019)		Odometer:	10044 km
Colour:	White/Blue			
Engine Capacity:	149 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	3.50-10	Rear Tyre Size:	130-70-10
Front Left Side:	Timsun 8 mm	Rear Left Side:	Timsun 8 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	186.00	99.00	87.00	46.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	560.00	459.00	101.00	18.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	746.00	558.00	188.00	25.20
+ GST 7.00/7.00% (\$\$)	52.22	39.06	13.16	25.20
Nett Amount (\$\$)	798.22	597.06	201.16	25.20

INSPECTION

Date of Assignment:	04/10/2021		
Date Inspected:	04/10/2021	Inspected At:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4 Singapore 539410
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 20 Oct 2021)	
Parts:	N/A	KYMC0 SUPER JOCKEY 150I 149cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBQ7277J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*CHAIN BOX (STAINLESS STEEL) 2MM	Not Necessary	10.00 F	*- FL
2	4		*HOOK HOLDER (S/STEEL)	Not Necessary	26.00 F	*- FL
3	1		*STICKER (SINGAPORE POST) BOX REAR	Necessary	70.00 F	*70.00 FL
4	1		*RUBBER SEAL REAR BOX	Necessary	80.00 FS	*36.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	186.00	106.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	7.00
Total Parts (S\$)	186.00	99.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT ON REAR BOX	New	260.00	250.00
2	REPAIR ON REAR BOX	New	84.00	84.00
3	TRANSPORT CHARGES (MOTORCYCLE) OVERSIZED-BIKE TOWED BACK TO BHH	New	90.00	0.00
4	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	126.00	125.00
Gross Labour Cost (\$)			560.00	459.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >