

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB21010200/KES3Q2  
**Date:** 27/12/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
<b>Claimant Vehicle No :</b>	SHC5196A	<b>Insured Vehicle No :</b>	SLS9063S
Date of Loss:	03/10/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0004455

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHC5196A</b>		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2H19749
Reg. Date:	20/11/2020 (Man. Year: 2020)	Chassis No:	JTDKB3FU303092735
Colour:	Metallic Pearl White/Red	Odometer:	56399 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Dunlop 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,020.02	990.27	6,029.75	85.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,560.00	710.00	8,850.00	92.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>16,580.02</b>	<b>1,700.27</b>	<b>14,879.75</b>	<b>89.75</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,160.60</b>	<b>119.02</b>	<b>1,041.58</b>	<b>89.74</b>

<b>Nett Amount (S\$)</b>	<b>17,740.62</b>	<b>1,819.29</b>	<b>15,921.33</b>	<b>89.75</b>
<hr/>				
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$96.30/day) (S\$)		288.90		
+ Doc/Search Fee (S\$)		7.49		
<hr/>				
<b>Nett Liability (S\$)</b>		<b>2,265.68</b>		
<hr/>				
<b>Global Sum Settlement (S\$)</b>		<b>2,260.00</b>		
<hr/>				

INSPECTION

Date of Assignment: 04/10/2021

Date Inspected: 05/10/2021

Estimated Period of Repair: 2.0 days

 Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)  
 2, Ang Mo Kio Street 63  
 Singapore 569111
**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 13 Dec 2021)
<b>Parts:</b>	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC5196A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Bent	485.60 FL	*485.60 FL
2	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Repair	332.70 FL	*- FL
3	1		*COVER ,REAR BUMPER LOWER	Serviceable	22.00 FL	*- FL
4	1		*GUARD ,REAR BUMPER ,CENTER	Dented	374.50 FL	*374.50 FL
5	1		*RETAINER ,REAR BUMPER SIDE ,LH	Distorted	132.60 FL	*132.60 FL
6	1		*RETAINER ,REAR BUMPER SIDE ,RH	Serviceable	132.60 FL	*- FL
7	1		*REFLECTOR ASSY ,REFLEX ,LH	Serviceable	39.00 FL	*- FL
8	1		*DUCT ASSY ,QUARTER VENT LH	Serviceable	67.00 FL	*- FL
9	1		*LENS & BODY ,REAR COMBINATION LAMP ,LH	Serviceable	339.60 FL	*- FL
10	1		*LENS & BODY ,REAR COMBINATION LAMP ,NO.2 LH	Cut	261.00 FL	*261.00 FL
11	1		*PANEL SUB-ASSY ,QUARTER ,LH	Repair	871.50 FL	*- FL
12	1		*LINER ,REAR WHEEL HOUSE ,LH	Serviceable	139.80 FL	*- FL
13	1		*COVER ,FLOOR UNDER NO.1 (LH)	Serviceable	175.10 FL	*- FL
14	1		*COVER ,REAR FLOOR (CTR)	Serviceable	229.90 FL	*- FL
15	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	651.00 FL	*- FL
16	1		*GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	Repair	913.60 FL	*- FL
17	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
18	1		*SET REAR BUMPER CLIP	Necessary	95.00 FS	*50.00 FS
19	1		*RIM	Serviceable	1,879.40 FS	*- FS
20	1		*TYRE	Serviceable	350.00 FS	*- FS
21	1		*REAR FENDER CLIP	Not Necessary	60.00 FS	*- FS
22	1		*REAR FENDER LINER CLIP	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,311.90</b>	<b>1,303.70</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,291.88	313.43
<b>Total Parts (\$\$)</b>	<b>7,020.02</b>	<b>990.27</b>

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,200.00	200.00
3	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
4	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	180.00	0.00
5	TO REMOVE AND REFIT ELECTRICAL WIRING BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWOK REPAIR	New	480.00	0.00
6	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	480.00	0.00
7	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT ,VACUUM AND CHARGE-IN-GAS	New	380.00	0.00
8	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
11	TOWING FEES	New	150.00	0.00
12	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	440.00
13	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
14	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
15	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
16	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
17	TO REPLACE ,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	0.00
18	TO LIFT-UP/OUT ENGINE WITH GEAR BOX AND REFIT	New	440.00	0.00
19	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS	New	380.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>9,560.00</b>	<b>710.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >