



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 7694K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LHR DOOR (SN)	DENTED	3,040.00	3,040.00
1	LHR DOOR SEAL (SN)	NECESSARY	100.33	100.33
1	LHR DOOR SEAL SIDE (SN)	NECESSARY	70.85	70.85
1	LHF DOOR (SN)	TO REPAIR SEE LABOUR	3,040.00	-
1	SOUND ABSORBER LAMINATED (SN)	NECESSARY	43.65	43.65
1	LHF DOOR SEAL (SN)	NOT NECESSARY	83.33	-
1	LONG-LIFE UNDERSEAL (SN)	NECESSARY	87.64	87.64
1	PROTECTIVE LHR FENDER FOIL (SN)	NECESSARY	43.38	43.38
			6,509.18	3,385.85
	<u>LABOUR</u>			
	B&P CHECK SHORY CIRCUIT / HARNESS REPAIR.	NOT NECESSARY	280.00	-
	B&P DIAGNOSIS AND PROGRAMMING.		480.00	480.00
	LABOUR. INCLUSIVE OF THE REPAIR OF LHF DOOR.		3,360.00	1,680.00
	TFR DOOR MECH.		1,680.00	420.00
	SPRAY PAINTING.		3,200.00	2,400.00
			9,000.00	4,980.00
	GRAND TOTAL		15,509.18	8,365.85
	RECOMMENDED COST OF REPAIRS			8,365.85

Report Ref No. CS/SMR21010202/Euce2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.