

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21010203/KPA3Q2**Date:** 09/06/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MCV0000229_02
Claimant Vehicle No : XD1416Y **Insured Vehicle No :** YN3402J
 Date of Loss: 01/10/2021 Nature of Claim: TP Claim No: MCV2021D0004318

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XD1416Y**
 Make & Model: ISUZU FVR34P, 17.6 D (M) Engine No: 6HK1450903
 Reg. Date: 11/06/2007 (Man. Year: 2007) Chassis No: JALFVR34P77000014
 Colour: White Odometer: 757564 km
 Engine Capacity: 7790 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D)
 Front Left Side: HILO 8 mm Rear Left Side: 6/6 mm
 Front Right Side: HILO 8 mm Rear Right Side: Progreen 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,186.85	5,384.50	1,802.35	25.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,160.00	2,580.00	580.00	18.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,346.85	7,964.50	2,382.35	23.02
Approved Total (Overridden) (S\$)		6,350.00		
(S\$)	10,346.85	6,350.00	3,996.85	38.63
+ GST 7.00/7.00% (S\$)	724.28	444.50	279.78	38.63
Nett Amount (S\$)	11,071.13	6,794.50	4,276.63	38.63
+ Loss of Use (8.0 x S\$150.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		8,002.50		
Global Sum Settlement (S\$)		8,000.00		

INSPECTION

Date of Assignment: 04/10/2021
 Date Inspected: 05/10/2021 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun Industrial Park A
 Singapore 768761
 Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Dec 2021)	
Parts:	N/A	ISUZU FVR34P 17.6 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD1416Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR	Bent	1,338.00 FL	*1,338.00 FL
2	1		*FRONT LH DOOR LOWER PROTECTOR	Missing	244.00 FL	*244.00 FL
3	1		*FRONT LH DOOR LOWER PROTECTOR COVER	Missing	25.00 FL	*25.00 FL
4	1		*SET FRONT LH DOOR PROTECTOR CLIPS	Necessary	39.00 FL	*39.00 FL
5	1		*FRONT LH DOOR KEY LOCK	Dented	64.00 FL	*64.00 FL
6	1		*FRONT LH DOOR INNER RUBBER (50%)	Cut	77.35 FS	*45.50 FS
7	1		*FRONT LH DOOR INNER LOCK	Repair	268.00 FL	*- FL
8	1		*FRONT LH MUDGUARD	Torn	481.00 FL	*481.00 FL
9	1		*FRONT LH MUDGUARD LAMP	Cracked	128.00 FL	*128.00 FL
10	1		*FRONT LH WHEEL ARP GARNISH	Cracked	292.00 FL	*292.00 FL
11	1		*SET FRONT LH WHEEL ARP GARNISH CLIPS	Necessary	45.00 FL	*45.00 FL
12	1		*CABIN REAR LH SIDE PANEL	Bent	754.00 FL	*754.00 FL
13	1		*REAR LH WHEEL MUDGUARD	Cracked	170.00 FL	*170.00 FL
14	1		*FRONT LH TYRE RIM	Dented	1,520.00 FL	*1,520.00 FL
15	1		*DIESEL TANK	Repair	1,702.00 FL	*- FL
16	1		*LH SAFETY BAR	Bent	620.00 FS	*620.00 FS
17	1		*FRONT LH TYRE (80%)	Punctured	480.00 FS	*384.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,247.35	6,149.50
- List Item Discount on L Items 15.00/15.00% (\$\$)	1,060.50	765.00
Total Parts (\$\$)	7,186.85	5,384.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT LH DOOR ,TRANSFER LOCK ASSY ,GARNISH ,REMOVE & REFIX PROTECTOR ,MUDGUARD ASSY ,WHEEL ARP GARNISH ,CUT ,WELD & RENEW CABIN REAR LH SIDE PANEL ,KNOCK & REPAIR INNER PANEL,FRT LH WHEEL ARP PANEL & REALIGN THE SAME	New	1,300.00	1,100.00
2	REMOVE & REFIX CABIN REAR LH SIDE PANEL GLASS	New	100.00	60.00
3	REMOVE & REFIX FRT LH DOOR GLASS	New	80.00	80.00
4	REMOVE & REFIX SEAT ,CARPET ,TOP ROOF LINING GARNISH	New	150.00	120.00
5	PUTTY & RESPRAY ON FRT LH DOOR ,PROTECTOR ,WHEEL ARP GARNISH ,CABIN REAR LH SIDE PANEL INNER & OUTER LH SIDE PANEL ,SAFETY BAR	New	1,000.00	900.00
6	REMOVE & REFIX DIESEL TANK AND REPAIR DIESEL TANK BRACKET	New	150.00	80.00
7	TO REWRITE ADVERTISEMENT	New	380.00	240.00
Gross Labour Cost (S\$)			3,160.00	2,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >