

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010206/KEA3Q2
Date: 09/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900257083
Claimant Vehicle No :	GBC4378U	Insured Vehicle No :	SFE8803A
Date of Loss:	30/09/2021	Nature of Claim:	TP
		Claim No:	8723343619SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC4378U	Engine No:	4D56UCZZ3169
Make & Model:	MITSUBISHI L200 D/CABIN, 2.5 D L 5MT TURBO D/AIRBAG 4WD (M)	Chassis No:	MMCJNKB40CD000298
Reg. Date:	16/05/2012 (Man. Year: 2011)	Odometer:	228683 km
Colour:	White		
Engine Capacity:	2477 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205 R16X8	Rear Tyre Size:	205 R16X8
Front Left Side:	Yokohama 4 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Yokohama 4 mm	Rear Right Side:	Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,622.80	5,234.28	1,388.52	20.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,730.00	1,400.00	1,330.00	48.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,352.80	6,634.28	2,718.52	29.07
Approved Total (Overridden) (S\$)		5,300.00		

(S\$)	9,352.80	5,300.00	4,052.80	43.33
+ GST 7.00/7.00% (S\$)	654.70	371.00	283.70	43.33
Nett Amount (S\$)	10,007.50	5,671.00	4,336.50	43.33
Global Sum Settlement (S\$)	0.00			

INSPECTION

Date of Assignment: 04/10/2021

Date Inspected: 04/10/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Kum Chew Motor Workshop (160 Sin Ming) (HQ)
 160 Sin Ming Drive, #05-08 Sin Ming Autocity
 Singapore 575722

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Bent	959.00 FL	*811.20 FL
2	8		*FRT BUMPER CLIPS	Necessary	86.40 FS	*60.00 FS
3	1		*FRT BUMPER REINFORCEMENT	Bent	337.00 FL	*337.00 FL
4	2		*FRT BUMPER RETAINER	Serviceable	70.00 FL	*- FL
5	2		*FRT BUMPER BRACKET	Distorted	170.00 FL	*170.00 FL
6	1		*FRT BUMPER LOWER GRILLE	Cracked	165.00 FL	*165.00 FL
7	1		*FRT BUMPER LOWER GARNISH	Bent	475.00 FL	*475.00 FL
8	4		*FRT BUMPER LOWER GARNISH CLIPS	Necessary	48.00 FL	*48.00 FL
9	1		*FRT GRILLE	Cracked	275.00 FL	*275.00 FL
10	2		*FRT HEADLAMP	Mtg Cracked	1,576.00 FL	*1,576.00 FL
11	1		*FRT HEADLAMP PANEL	Repair	899.00 FL	*- FL
12	1		*FRT NUMBER PLATE HOUSING	Bent	42.00 FL	*42.00 FL
13	1		*FRT CROSS MEMBER	Bent	367.00 FL	*367.00 FL
14	1		*FRT MITSUBISHI EMBLEM	Necessary	56.00 FL	*56.00 FL
15	1		*FRT INTERCOOLER	Punctured	1,011.00 FL	*1,011.00 FL
16	1		*FRT INTERCOOLER PIPE	Serviceable	114.00 FL	*- FL
17	1		*FRT NUMBER PLATE WITH CASING	Bent	60.00 FS	*45.00 FS
18	1		*REAR LAMP -L/H	Cut	465.00 FL	*366.00 FL
19	1		*REAR REFLECTOR -L/H (CRACKED)	Not Consistent With The Impact	167.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,342.40	5,804.20
- List Item Discount on L Items 10.00/10.00% (\$\$)	719.60	569.92
Total Parts (\$\$)	6,622.80	5,234.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PULL ,KNOCK ON FRT ACCIDENT PORTION & CHARGE THE ABOVE PARTS	New	850.00	500.00
2	TO SPRAY PAINT ON FRT ACCIDENT PORTION	New	680.00	400.00
3	TO CHECK WIRING FUNCTIONS	New	60.00	20.00
4	TO ANTI-RUST AFFECTED AREAS	New	150.00	0.00
5	TO DISMANTLE & REPLACE INTERCOOLER	New	150.00	60.00
6	TO PULL KNOCK ON REAR ACCIDENT PORTION & CHARGE THE ABOVE PARTS	New	280.00	200.00
7	TO SPRAY & PAINT ON REAR ACCIDENT PORTION	New	480.00	200.00
8	TO ANTI-RUST REAR AFFECTED AREAS	New	50.00	0.00
9	TO CHECK WIRING FUNCTIONS	New	30.00	20.00
Gross Labour Cost (\$\$)			2,730.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >