



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KHOR SAW THENG			Ref: CC4/ASM21010207/Ags3q2 Date: 24/01/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SMJ 7824L	Veh. Inspected	SJQ 8814H
	Policy No.	GA568014	Coverage (\$)	0.00
	Claim No.	S1M03J65	Excess (\$)	0.00
	Assign From		Assign Date	04/10/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HYUNDAI AVANTE	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	KMH DU41BR9U770132	Colour	MAROON
	Odometer	61434 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	185/65 R15	MICHELIN	6 mm
	L/H Front Tyre	185/65 R15	MICHELIN	6 mm
	R/H Rear Tyre	185/65 R15	MICHELIN	6 mm
	L/H Rear Tyre	185/65 R15	MICHELIN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	01/10/2021	Inspection Date	04/10/2021
	Survey held at	CN MOTORS PTE LTD 1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>6 Working Days</b>