

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010215/T1UCN2**Date:** 19/11/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00013492100
Claimant Vehicle No :	CB7985R	Insured Vehicle No :	YN2428S
Date of Loss:	01/10/2021	Nature of Claim:	TP
		Claim No:	SNM21D205602/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	CB7985R		
Make & Model:	TOYOTA HIACE, 3.0 D COMMUTER GL AT 2WD 4DR LWB (M)	Engine No:	1KD2672873
Reg. Date:	15/11/2017 (Man. Year: 2016)	Chassis No:	KDH2118007622
Colour:	Grey	Odometer:	155336 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	195R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,279.12	3,439.80	839.32	19.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,670.00	1,070.00	600.00	35.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,949.12	4,509.80	1,439.32	24.19
Approved Total (Overridden) (\$\$)		3,600.00		
(\$\$)	5,949.12	3,600.00	2,349.12	39.49
+ GST 7.00/7.00% (\$\$)	416.44	252.00	164.44	39.49
Nett Amount (\$\$)	6,365.56	3,852.00	2,513.56	39.49

INSPECTION

Date of Assignment:	04/10/2021	
Date Inspected:	04/10/2021	Inspected At: Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68 Singapore 575643
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 19 Nov 2021)	
Parts:	N/A	TOYOTA HIACE 3.0 D COMMUTER GL AT 2WD 4DR LWB (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for CB7985R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT DOOR LH	Bent	1,438.50 FL	*1,438.50 FL
2	1	*FRONT DOOR WING MIRROR LH	Broken	998.00 FL	*998.00 FL
3	1	*FRONT DOOR WEATHERSTRIP	Cut	209.50 FL	*209.50 FL
4	1	*FRONT DOOR BOTTOM RUBBER	Cut	69.20 FL	*69.20 FL
5	1	*FRONT DOOR OUTER MOULDING	Cut	109.50 FL	*109.50 FL
6	1	*FRONT DOOR GLASS LH	Cut	419.00 FL	*419.00 FL
7	1	*FRONT DOOR GLASS SEAL	Not Necessary	72.00 FL	*- FL
8	1	*FRONT DOOR CHANNEL	Not Necessary	215.00 FL	*- FL
9	1	*FRONT DOOR INNER TRIM LH	Not Necessary	672.10 FL	*- FL
10	1	*SET FRONT DOOR INNER TRIM CLIPS	Not Necessary	40.00 FL	*- FL
11	1	*FRONT SIDE THIRD WING MIRROR LH	Cut	196.20 FL	*196.20 FL
12	1	*WIPER GARNISH LH	Cut	243.50 FL	*243.50 FL
13	1	*HEADLAMP ASSY LH	Cracked	623.00 FL	*623.00 FL
14	1	*SET FRONT DOOR SUN VISOR	Necessary	250.00 FS	*180.00 FS
15	1	*SET FRONT DOOR WING MIRROR CHROME STICKER HELLA	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,605.50	4,516.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,326.38	1,076.60
Total Parts (\$\$)	4,279.12	3,439.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	500.00	350.00
2	SPRAY PAINTING	New	1,000.00	600.00
3	CHECK WIRING	New	30.00	30.00
4	ANTI RUST	New	50.00	30.00
5	REMOVE AND INSTALL FRONT DOOR PARTS	New	90.00	60.00
Gross Labour Cost (\$)			1,670.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >