

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010217/EVCN2**Date:** 26/10/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNW00005192100

**Claimant Vehicle
No :** FBM1880C**Insured
Vehicle No :** SML9849S

Date of Loss: 29/06/2021

Nature of Claim: TP

Claim
No: SNM21D203979/C02/TANKL**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **FBM1880C**

Make & Model: SYM COMBIZ 125, 125cc

Engine No: KZ703327

Reg. Date: 07/08/2017 (Man. Year: 2017)

Chassis No: RFGAPA301HS003321

Colour: White

Odometer: 34172 km

Engine Capacity: 125 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	3.50-10	Rear Tyre Size:	3.50-10
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,178.00	838.50	339.50	28.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	370.00	300.00	70.00	18.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,548.00	1,138.50	409.50	26.45
Approved Total (Overridden) (S\$)		900.00		
(S\$)	1,548.00	900.00	648.00	41.86
+ GST 7.00/7.00% (S\$)	108.36	63.00	45.36	41.86
Nett Amount (S\$)	1,656.36	963.00	693.36	41.86

INSPECTION

Date of Assignment: 04/10/2021

Date Inspected: 05/10/2021 Inspected At:

Unique Motorsports Pte Ltd (Toh Guan)
48 Toh Guan Road East, #02-140 Enterprise Hub
Singapore 608586

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Oct 2021)	
Parts:	N/A	SYM COMBIZ 125 125cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBM1880C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*STICKER SINGPOST-FIBER BOX	Necessary	160.00 F	*120.00 FL
2	1		*MIRROR SET	Cut	65.00 F	*45.00 FL
3	1		*BRAKE LEVER	Broken	45.00 F	*30.00 FL
4	1		*EXHAUST PROTECTOR	Broken	75.00 F	*60.00 FL
5	1		*SIDE STAND ASSY	Bent	118.00 F	*100.00 FL
6	1		*FRONT UNDER SPOILER	Cut	170.00 F	*140.00 FL
7	1		*FRONT COVER SUB ASSY	Cut	240.00 F	*180.00 FL
8	1		*FRONT FENDER	Cut	105.00 F	*90.00 FL
9	1		*FIBER BOX (RESpray)	Cut	200.00 FS	*150.00 FS
					Sub Total (\$\$)	1,178.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00
					Total Parts (\$\$)	838.50

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RESPRAY & PUTTY WORKS	New	120.00	100.00
2	LABOUR COST	New	250.00	200.00
Gross Labour Cost (S\$)			370.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >