

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21010221/R1VCN2**Date:** 28/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900081072
Claimant Vehicle No :	GBF9630S	Insured Vehicle No :	GQ4359S
Date of Loss:	30/09/2021	Nature of Claim:	TP
		Claim No:	6345301349SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF9630S	Engine No:	4P10C48879
Make & Model:	mitsubishi canter, 3.0 D (M)	Chassis No:	FEA01BA20519
Reg. Date:	26/04/2017 (Man. Year: 2016)	Odometer:	158673 km
Colour:	White		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/75R15	Rear Tyre Size:	155R12C(D)
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 5/5 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	04/10/2021	
Date Inspected:	26/10/2021	Inspected At: BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969 REPAIRER: ENG SOON PAINTING SVC
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$50,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Bent	0.00 F	*- F
2	1		*FRT BUMPER SIDE GARNISH LH	Deformed	0.00 F	*- F
3	1		*FRT CORNER PANEL LH	Bent	0.00 F	*- F
4	1		*FRT LH HEADLAMP ASSY	Broken	0.00 F	*- F
5	1		*FRT SIDE MIRROR (ROUND) STAY LH	Bent	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >