

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21010222/DGA3Q2**Date:** 17/08/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SHB2700U	Insured Vehicle No :	SLR8461M
Date of Loss:	01/10/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0004461

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB2700U		
Make & Model:	HYUNDAI AE IONIQ, 1.6 (A)	Engine No:	G4LEKU386816
Reg. Date:	27/11/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVLU183633
Colour:	Yellow	Odometer:	0 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	71,747.27	35,638.45	36,108.82	50.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,770.00	3,610.00	5,160.00	58.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	80,517.27	39,248.45	41,268.82	51.25
Approved Total (Overridden) (S\$)		28,000.00		
(S\$)	80,517.27	28,000.00	52,517.27	65.22
+ GST 7.00/7.00% (S\$)	5,636.21	1,960.00	3,676.21	65.22
Nett Amount (S\$)	86,153.48	29,960.00	56,193.48	65.22
+ Loss of Use (16.0 x S\$40.00/day) (S\$)		640.00		
+ Car Rental (16.0 x S\$125.19/day) (S\$)		2,003.04		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		160.00		
Nett Liability (S\$)		32,770.49		
Global Sum Settlement (S\$)		32,770.00		

INSPECTION

Date of Assignment:	04/10/2021	
Date Inspected:	05/10/2021	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	14.0 days	

8/17/22, 8:55 AM

Adjuster Report

Adjuster: BRYAN TANI

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jun 2022)
Parts:	143	HYUNDAI AE IONIQ 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB2700U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	2,253.80 FL	*2,253.80 FL
2	2		*BONNET HINGE (LH/RH)	Bent	237.40 FL	*237.40 FL
3	1		*BONNET MOULDING	Not fitted	41.40 FL	*- FL
4	1		*BONNET LOCK	Bent	127.30 FL	*127.30 FL
5	1		*BONNET INSULATOR	Not Necessary	230.10 FL	*- FL
6	1		*BONNET INSULATOR CLIPS	Serviceable	15.00 FL	*- FL
7	1		*BONNET CABLE	Not Necessary	135.60 FL	*- FL
8	1		*RADIATOR GRILLE NEW MODEL	Cut	1,568.60 FL	*1,568.60 FL
9	1		*FLAP ASSY ACTIVE AIR UPPER (LH/RH)	O/S Cracked / N/SNot Necessary	1,649.20 FL	*824.60 FL
10	1		*UNIT ASSY -SMART CRU (RADAR SENSOR)	Not Necessary	2,910.90 FL	*- FL
11	1		*FLAP ASSY ACTIVE WIRE	Socket Broken	765.30 FL	*765.30 FL
12	1		*FRONT NUMBER PLATE GARNISH	Deformed	188.00 FL	*188.00 FL
13	1		*FRONT BUMPER COVER	Torn	418.30 FL	*418.30 FL
14	1		*FRONT BUMPER TOP COVER	Cracked	476.30 FL	*476.30 FL
15	1		*FRONT BUMPER SPONGE	Torn	186.90 FL	*186.90 FL
16	1		*FRONT BUMPER REINFORCEMENT	Dented / Bent	1,075.10 FL	*650.00 FL
17	2		*FRONT BUMPER REINFORCEMENT ABSORBER (LH/RH)	Bent	373.00 FL	*373.00 FL
18	1		*FRONT BUMPER TOWING COVER	Distorted	29.00 FL	*29.00 FL
19	1		*FRONT BUMPER MOULDING CENTRE UPPER	Broken	368.50 FL	*368.50 FL
20	1		*FRONT BUMPER MOULDING	Not fitted	93.60 FL	*- FL
21	1		*FRONT BUMPER LOWER STIFFNER	Serviceable	285.10 FL	*- FL
22	1		*FRONT BUMPER LOWER GRILLE	Cracked	365.30 FL	*365.30 FL
23	1		*FRONT BUMPER LOWER GRILLE MOULDING	Cut	127.60 FL	*127.60 FL
24	1		*FRONT BUMPER LIP	Serviceable	35.10 FL	*- FL
25	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	70.00 FL	*- FL
26	1		*FRONT BUMPER BRACKET (LH/RH)	O/S Dislodged /N/S Serviceable	56.00 FL	*28.00 FL
27	2		*FRONT BUMPER RETAINER MOUNTING (LH/RH)	Not Necessary	130.60 FL	*- FL
28	10		*FRONT BUMPER CLIPS	Necessary	25.00 FL	*25.00 FL
29	1		*FRONT BUMPER GRILLE (LH/RH)	O/S Dislodged/N/S NotNecessary	373.80 FL	*186.90 FL
30	1		*DAY LIGHT ,RH	Dislodged	642.50 FL	*642.50 FL
31	1		*DAY LIGHT WIRE	Torn	585.50 FL	*585.50 FL
32	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	949.30 FL	*949.30 FL
33	2		*HEADLAMP (LH/RH)	Broken	7,974.60 FL	*3,987.30 FL
34	2		*HORN UNIT (LH/RH)	Not Necessary	145.60 FL	*- FL
35	1		*HORN WIRE	Not Necessary	386.70 FL	*- FL
36	1		*RADIATOR INVERTER	Bent	884.80 FL	*884.80 FL
37	1		*RADIATOR	Bent	710.50 FL	*710.50 FL
38	1		*RADIATOR FAN BLOWER MOTOR ASSY	Not Necessary	1,226.60 FL	*- FL
39	2		*RADIATOR AIR GUARD (LH/RH)	Serviceable	152.80 FL	*- FL
40	2		*RADIATOR AIR GUARD ,UPR (LH/RH)	Not Necessary	255.00 FL	*- FL
41	2		*FRT PILLAR UPPER COVER -OUTER (LH)	Not Necessary	179.20 FL	*- FL
42	2		*FRONT FENDER (LH/RH)	Dented	981.40 FL	*981.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FRONT FENDER UPPER GARNISH (RH)	Dislodged	196.80 FL	*196.80 FL
44	1		*FRONT FENDER APRON PANEL (RH)	Not Necessary	756.20 FL	*- FL
45	1		*FRONT FENDER APRON PANEL UPPER (RH)	Not Necessary	329.00 FL	*- FL
46	1		*FRONT CHASIS MEMBER (RH)	Not Necessary	1,314.80 FL	*- FL
47	1		*FRONT FENDER SHIELD (LH/RH)	O/S Torn / N/S Not Necessary	329.40 FL	*164.70 FL
48	1		*AIRCON CONDENSER	Bent	663.60 FL	*663.60 FL
49	1		*AIRCON SUCTION & LIQUID HOSE	Bent	679.60 FL	*679.60 FL
50	1		*AIRCON METAL HOSE -SMALL	Not Necessary	186.50 FL	*- FL
51	1		*AIRCON METAL HOSE -BIG	Not Necessary	352.10 FL	*- FL
52	1		*AIRCON DISCHARGE HOSE	Bent	148.50 FL	*148.50 FL
53	2		*FRT DOOR (LH/RH)	Dented	3,594.40 FL	*3,594.40 FL
54	2		*FRONT DOOR HINGE UPPER (LH/RH)	Not Necessary	331.52 FL	*- FL
55	2		*FRONT DOOR HINGE LOWER (LH/RH)	Not Necessary	307.40 FL	*- FL
56	2		*FRONT DOOR CHECK (LH/RH)	Not Necessary	145.96 FL	*- FL
57	1		*FRONT DOOR MIRROR ASSY (LH)	Not Necessary	1,691.70 FL	*- FL
58	1		*FRONT DOOR PROTECTOR (RH)	Serviceable	186.20 FL	*- FL
59	2		*FRT SAFETY BELT (ASSY) (LH/RH)	Activated	1,297.80 FL	*1,297.80 FL
60	2		*REAR SAFETY BELT (ASSY) (LH/RH)	Activated	1,026.40 FL	*1,026.40 FL
61	2		*REAR SAFETY BELT GARNISH COVER (LH/RH)	Cracked / Broken	796.00 FL	*796.00 FL
62	1		*ROCKER PANEL OUTER GARNISH (RH)	Bent	715.60 FL	*715.60 FL
63	1		*WIPER BLADE	Not Necessary	46.00 FL	*- FL
64	1		*WIPER MOTOR	Not Necessary	319.60 FL	*- FL
65	1		*WIPER SPARE TANK MOTOR	Dislodged	378.56 FL	*378.56 FL
66	1		*WIPER ARM	Not Necessary	133.60 FL	*- FL
67	1		*WIPER LINK	Not Necessary	224.00 FL	*- FL
68	1		*WIPER TOP GARNISH	Not Necessary	681.20 FL	*- FL
69	1		*WIPER TOP GARNISH SIDE COVER (RH)	Not Necessary	86.40 FL	*- FL
70	1		*WIPER CONTAINER ASSY	Broken	385.40 FL	*385.40 FL
71	1		*FRONT WHEEL RIM (LH/RH)	O/S Distorted/N/S Not Necessary	2,248.40 FL	*1,124.20 FL
72	2		*FRONT WHEEL HUB CAP AND HUB ASSY (LH/RH)	Not Necessary	1,357.00 FL	*- FL
73	1		*FRONT WHEEL HUB CAP	N/S Serviceable/ O/SCut/Broken	692.80 FL	*346.40 FL
74	2		*TYRE PRESSURE SENSOR	Not Necessary	1,305.60 FL	*- FL
75	1		*FRONT SHOCK ABSORBER (ASSY) (LH/RH)	O/SDistorted/N/S Not Necessary	745.00 FL	*372.50 FL
76	2		*FRONT SHOCK ABSORBER MOUNTING (LH/RH)	Not Necessary	745.00 FL	*- FL
77	2		*FRONT DRIVE SHAFT (LH/RH)	Not Necessary	2,273.40 FL	*- FL
78	1		*FRONT DRIVE SHAFT EXTENSION RH	Not Necessary	1,125.80 FL	*- FL
79	1		*RACK & PINION ASSY	Not Necessary	2,387.40 FL	*- FL
80	2		*STG TIE ROD	Not Necessary	251.20 FL	*- FL
81	2		*STG TIE END	Not Necessary	189.40 FL	*- FL
82	2		*STABILIZER BAR	Not Necessary	653.60 FL	*- FL
83	2		*STABILIZER BAR LINK	Not Necessary	184.20 FL	*- FL
84	1		*FRONT SUSPENSION LOWER ARM (LH/RH)	O/SDistorted/N/S Not Necessary	1,193.60 FL	*296.80 FL
85	1		*KNUCKLE ARM (LH/RH)	O/SDistorted/N/S Not Necessary	1,327.20 FL	*363.60 FL
86	2		*ABS SENSOR	Not Necessary	580.00 FL	*- FL
87	1		*ROOF UPHOLSTERY LINING	Crumpled	1,983.30 FL	*1,983.30 FL
88	1		*DASHBOARD COMPLETE	Broken	4,724.00 FL	*1,474.00 FL
89	1		*STEERING AIRBAG COMPLETE	Activated	1,090.90 FL	*1,090.90 FL
90	1		*AIRBAG CONTROL MODULE	Activated	1,243.70 FL	*1,243.70 FL
91	1		*CURTAIN AIRBAG MODULE (RH)	Activated	1,344.50 FL	*1,344.50 FL
92	1		*KNEE CONTROL AIRBAG MODULE ASSY	Activated	578.60 FL	*578.60 FL
93	1		*AIR BAG ASSY -PASSENGER	Activated	1,951.20 FL	*1,951.20 FL
94	1		*STEERING ANGLE ASSY	Socket Broken	786.90 FL	*786.90 FL
95	1		*SENSOR ASSY IMPACT -FRT INPACT	Activated	643.90 FL	*643.90 FL
96	2		*AIRBAG SENSOR (LH/RH)	Not Necessary	696.20 FL	*- FL
97	1		*FRONT NUMBER PLATE }	Cut / Bent	25.00 FS	*45.00 FS

Report was unsubmitted during this print-out.

8/17/22, 8:55 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
98	1		*FRONT NO PLATE TRIM COVER }	Cracked	30.00 FS	*- FS
99	1		*COOLANT	Not Necessary	45.00 FS	*- FS
100	1		*EMBLEM -BLUE DRIVE (RH)	Necessary	26.60 FS	*26.60 FS
101	2		*FRONT DOOR CITY CAB LOGO (LH/RH)	Necessary	150.00 FS	*150.00 FS
102	2		*FRONT TYRE (LH/RH)	Not Necessary	432.00 FS	*- FS
103	1		*ENGINE UNDER COVER	Torn	469.40 FL	*469.40 FL
104	1		*AIRBAG FRT SEAT (RH)	Activated	1,344.50 FL	*1,344.50 FL
105	1		*FRONT SEAT (RH)	Repair	5,183.20 FL	*- FL
106	1		*AIR CLEANER ASSY	Not Necessary	1,336.50 FL	*- FL
107	1		*ENGINE MOUNTING	Damaged	786.20 FL	*483.00 FL
108	1		*OIL CONTROL VALVE	Socket Broken	385.20 FL	*385.20 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)						89,506.94 44,492.66
- List Item Discount on L Items 20.00/20.00% (\$\$)						17,759.67 8,854.21
Total Parts (\$\$)						71,747.27 35,638.45
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,200.00	1,300.00
2	SPRAY PAINTING CHARGE	New	2,200.00	1,200.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	TRANSFER OF DOOR MECHANISM FRONT	New	160.00	120.00
7	RE-SET FRT POWER WINDOW SYSTEM	New	400.00	0.00
8	FOUR WHEEL ALIGNMENT	New	120.00	60.00
9	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	150.00
10	RE-SET FRT ABS SYSTEM	New	200.00	0.00
11	REMOVE/REFIX RADIATOR	New	90.00	50.00
12	REMOVE/REFIX FRONT WINDSCREEN GLASS	New	120.00	80.00
13	REMOVE/REFIX REAR UNDERCARRIAGE	New	280.00	0.00
14	FRONT CHASSIS ALIGNMENT CHARGE	New	220.00	0.00
15	REMOVE/REFIX AIR BAG/STEERING WHEEL/DASHBOARD /SEAT	New	550.00	250.00
16	REMOVE/REFIX ROOF TOP LINING	New	450.00	150.00
17	RE-PROGRAME AIR BAG & SAFETY BELT SYSTEM }	New	550.00	180.00
18	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	550.00	0.00
Gross Labour Cost (\$\$)			8,770.00	3,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >