

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010223/EPA3Q2**Date:** 19/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100075932
Claimant Vehicle No :	GBH977R	Insured Vehicle No :	SJE7268D
Date of Loss:	23/09/2021	Nature of Claim:	TP
		Claim No:	9044046599SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH977R		
Make & Model:	NISSAN NV200, 1.5 D MT ABS AIRBAG 2WD 6DR (A)	Engine No:	K9KC400D057850
Reg. Date:	30/12/2017 (Man. Year: 2017)	Chassis No:	VSKYBAM20Z0152781
Colour:	Grey	Odometer:	116728 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,175.04	2,906.67	1,268.37	30.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,100.00	1,880.00	1,220.00	39.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,275.04	4,786.67	2,488.37	34.20
Approved Total (Overridden) (S\$)		3,850.00		
(S\$)	7,275.04	3,850.00	3,425.04	47.08
+ GST 7.00/7.00% (S\$)	509.25	269.50	239.75	47.08
Nett Amount (S\$)	7,784.29	4,119.50	3,664.79	47.08
+ Loss of Use (6.0 x S\$70.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,541.50		

INSPECTION

Date of Assignment:	04/10/2021	
Date Inspected:	07/12/2021 Inspected At:	Efficient Motor & Engineering Works Pte Ltd (HQ) 56 Loyang Way #06-07, Loyang Enterprise Building Singapore 508775
Estimated Period of Repair:	6.0 days	

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Dented	555.20 FL	*555.20 FL
2	1		*FRONT FENDER SIGNAL LAMP LH	Not Necessary	61.60 FL	*- FL
3	1		*FRONT DOOR LH	Dented	1,287.50 FL	*1,287.50 FL
4	2		*FRONT DOOR HINGE LH	Not Necessary	117.80 FL	*- FL
5	1		*ROCKER PANEL LH	Dented	1,353.60 FL	*1,353.60 FL
6	1		*SLIDING DOOR LH	Repair	1,229.90 FL	*- FL
7	1		*DOOR CO REG STICKER	Necessary	30.00 FS	*30.00 FS
					Sub Total (\$)	4,635.60
					- List Item Discount on L Items 10.00/10.00% (\$)	460.56
					Total Parts (\$)	4,175.04

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT & WELD LH ROCKER PANEL ,PANEL BEAT & REPLAC LH FRONT FENDER AND DAMAGED PARTS	New	1,200.00	1,000.00
2	TO TRANSFER LH FRONT DOOR PARTS AND MECHANISMS TO NEW DOOR	New	150.00	50.00
3	TO TRANSFER LH SLIDING DOOR PARTS AND MECHANISM TO NEW DOOR	New	150.00	0.00
4	TO CHECK AND RECTIFY LIGHTING & WIRING	New	80.00	30.00
5	TO SPRAY PAINT LH FRONT FENDER ,LH FRONT DOOR ,LH SLIDING DOOR ,LH ROCKER PANEL	New	1,400.00	800.00
6	TO CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (\$\$)			3,100.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >