

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III21010228/R1EA3Q2**Date:** 08/04/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MCV0000961\_01

**Claimant Vehicle No :** SG5980B **Insured Vehicle No :** PC3006J

Date of Loss: 27/09/2021 Nature of Claim: TP Claim No: MCV2021D0004250

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SG5980B**  
 Make & Model: MAN A95, 10.5 D (A) Engine No: 50351050855104  
 Reg. Date: 19/11/2018 (Man. Year: 2018) Chassis No: WMAA95ZZ8JF007790  
 Colour: Green Odometer: 295237 km  
 Engine Capacity: 10518 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)  
 Front Left Side: Falken 8 mm Rear Left Side: Falken 8/8 mm  
 Front Right Side: Falken 8 mm Rear Right Side: Falken 8/8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	429.98	429.98	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	960.00	980.00	50.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,369.98</b>	<b>1,389.98</b>	<b>980.00</b>	<b>41.35</b>
<b>+ GST 7.00/7.00% (S\$)</b>	165.90	97.30	68.60	41.35
<b>Nett Amount (S\$)</b>	<b>2,535.88</b>	<b>1,487.28</b>	<b>1,048.60</b>	<b>41.35</b>
<b>+ Loss of Use (4.0 x S\$325.00/day) (S\$)</b>		1,300.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>2,794.73</b>		

INSPECTION

Date of Assignment: 04/10/2021

Date Inspected: 05/10/2021 Inspected At:

310 MANDAI RD

Repairer: Tower Transit Singapore Pte Ltd (HQ)

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD RASUL**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 15 Mar 2022)	
Parts:	N/A	MAN A95 10.5 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SG5980B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOWER TRANSIT LOGO (B)	Necessary	120.00 F	*120.00 F
2	1		*MATERIAL COST	Necessary	309.98 F	*309.98 F
F=Franchise part.						
Total Parts (S\$)					429.98	429.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PERFORM REPAIR WORKS ON : REAR ENGINE DOOR ASSY	New	1,300.00	320.00
2	SPRAY PAINTING :REAR ENINE DOOR	New	640.00	640.00
<b>Gross Labour Cost (\$)</b>			<b>1,940.00</b>	<b>960.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >