

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

India International Insurance Pte Ltd  
64 Cecil Street, #04-00 IOB Building  
Singapore 049711

**Our File No:** CS/III21010240/R1TF3N2**Date:** 25/10/2021**REFERENCE**

|                   |             |                  |                  |                           |
|-------------------|-------------|------------------|------------------|---------------------------|
| Insured/Claimant: | K.U.S METAL | Policy No:       | D19MCV0000229_02 |                           |
| Date of Loss:     | 01/10/2021  | Nature of Claim: | OD               | Claim No: MCV2021D0004318 |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                    |             |              |
|-----------------------------|------------------------------------|-------------|--------------|
| Reg No:                     | <b>YN3402J</b>                     |             |              |
| Make & Model:               | MITSUBISHI FE83BE6SRDEA, 3.0 D (A) | Engine No:  | 4M42A91339   |
| Reg. Date:                  | 04/01/2013 (Man. Year: 2012)       | Chassis No: | FE83BEA20939 |
| Colour:                     | White                              | Odometer:   | 319302 km    |
| Engine Capacity:            | 2977 cc                            |             |              |
| Market Value/New Car Price: | S\$24,000.00                       |             |              |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>  |             |              |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |                  |                  |                    |
|-------------------|------------------|------------------|--------------------|
| Front Tyre Size:  | 7.00 R16         | Rear Tyre Size:  | 185 R14C (D)       |
| Front Left Side:  | Double Star 7 mm | Rear Left Side:  | Double Star 7/7 mm |
| Front Right Side: | Double Star 7 mm | Rear Right Side: | Double Star 7/7 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 15,085.92         | 13,345.69         | 1,740.23          | 11.54         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 3,810.00          | 2,820.00          | 990.00            | 25.98         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>18,895.92</b>  | <b>16,165.69</b>  | <b>2,730.23</b>   | <b>14.45</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>12,900.00</b>  |                   |               |
| <b>- Excess (S\$)</b>                    | 750.00            | 750.00            | 0.00              | 0.00          |
| <b>(S\$)</b>                             | 18,145.92         | 12,150.00         | 5,995.92          | 33.04         |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 1,270.21          | 850.50            | 419.71            | 33.04         |
| <b>Nett Amount (S\$)</b>                 | <b>19,416.13</b>  | <b>13,000.50</b>  | <b>6,415.63</b>   | <b>33.04</b>  |

**INSPECTION**

|                             |                          |                                                                                                                                              |
|-----------------------------|--------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 05/10/2021               |                                                                                                                                              |
| Date Inspected:             | 05/10/2021 Inspected At: | CYS Automobile Services Pte Ltd (Woodlands)<br>38 Woodlands Industrial Park East 1, #07-17,<br>Admiralty Industrial Park<br>Singapore 757700 |
| Estimated Period of Repair: | 12.0 days                |                                                                                                                                              |

**Adjuster:** MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                     |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------|
| <b>Part Source:</b>  | (Last Synchronised: 23 Oct 2021)                                                                                                                                             |                                                                     |
| <b>Parts:</b>        | N/A                                                                                                                                                                          | mitsubishi FE83BE6SRDEA 3.0 D (A) (Model not available in database) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                   |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for YN3402J)                                                                                                                                     |                                                                     |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                     |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                     |

### Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition     | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *FRONT WINDSCREEN GLASS               | Cracked       | 1,338.08 FL | *1,338.08 FL |
| 2   | 1   |          | *FRONT WINDSCREEN GLASS RUBBER        | Necessary     | 387.00 FL   | *387.00 FL   |
| 3   | 1   |          | *FRONT WINDSCREEN PILLAR RH           | Bent          | 1,240.95 FL | *1,240.95 FL |
| 4   | 1   |          | *WIPER ARM,WIPER BLADE,WIPER COVER    | Scratched     | 129.82 FL   | *129.82 FL   |
| 5   | 1   |          | *WIPER GRILLE                         | Scratched     | 383.26 FL   | *383.26 FL   |
| 6   | 1   |          | *WIPER GRILLE CANTER STICKER          | Necessary     | 84.37 FL    | *84.37 FL    |
| 7   | 1   |          | *FRONT CORNER PANEL RH                | Buckled       | 398.41 FL   | *398.41 FL   |
| 8   | 1   |          | *FRONT CORNER PANEL LOWER RUBBER RH   | Necessary     | 25.92 FL    | *25.92 FL    |
| 9   | 1   |          | *SIDE MIRROR RH                       | Broken        | 107.67 FL   | *107.67 FL   |
| 10  | 1   |          | *SIDE MIRROR BRACKET RH               | Cracked       | 252.90 FL   | *252.90 FL   |
| 11  | 1   |          | *SIDE MIRROR COVER RH                 | Missing       | 64.03 FL    | *64.03 FL    |
| 12  | 1   |          | *FRONT PANEL                          | Bent          | 1,115.92 FL | *1,115.92 FL |
| 13  | 1   |          | *FRONT GRILLE                         | Scratched     | 383.26 FL   | *383.26 FL   |
| 14  | 1   |          | *FRONT GRILLE EMBLEM                  | Necessary     | 57.12 FL    | *57.12 FL    |
| 15  | 1   |          | *FRONT GRILLE FUSO EMBLEM             | Necessary     | 107.24 FL   | *107.24 FL   |
| 16  | 1   |          | *FRONT GRILLE CLIPS<br>(8 Pcs)        | Necessary     | 80.00 FL    | *80.00 FL    |
| 17  | 1   |          | *HEADLAMP ASSY RH                     | Broken        | 721.25 FL   | *721.25 FL   |
| 18  | 1   |          | *HEADLAMP LOWER RUBBER RH             | Missing       | 15.00 FL    | *15.00 FL    |
| 19  | 1   |          | *SIGNAL LAMP RH                       | Broken        | 206.01 FL   | *206.01 FL   |
| 20  | 1   |          | *SIDE LAMP RH                         | Broken        | 139.05 FL   | *139.05 FL   |
| 21  | 1   |          | *FRONT BUMPER                         | Bent          | 999.86 FL   | *999.86 FL   |
| 22  | 1   |          | *FRONT BUMPER BRACKET                 | Bent          | 151.71 FL   | *151.71 FL   |
| 23  | 1   |          | *FRONT DOOR RH                        | Bent          | 1,910.15 FL | *1,910.15 FL |
| 24  | 1   |          | *FRONT DOOR OUTER GARNISH RH          | Scratched     | 51.35 FL    | *51.35 FL    |
| 25  | 1   |          | *FRONT DOOR TOP MOULDING RH           | Scratched     | 100.15 FL   | *100.15 FL   |
| 26  | 1   |          | *FRONT DOOR OUTER MOULDING RH         | Not Necessary | 120.00 FL   | *- FL        |
| 27  | 2   |          | *FRONT DOOR HINGES                    | Bent          | 263.20 FL   | *263.20 FL   |
| 28  | 1   |          | *FRONT DOOR WEATHERSTRIP RH           | Necessary     | 408.22 FL   | *408.22 FL   |
| 29  | 1   |          | *FRONT DOOR INNER TRIM BOARD RH       | Not Necessary | 541.25 FL   | *- FL        |
| 30  | 1   |          | *FRONT DOOR INNER LOCK RH             | Serviceable   | 535.76 FL   | *- FL        |
| 31  | 1   |          | *FRONT DOOR REGULATOR GEAR WITH MOTOR | Serviceable   | 1,028.59 FL | *- FL        |
| 32  | 1   |          | *FRONT DOOR JACK RH                   | Bent          | 78.60 FL    | *78.60 FL    |
| 33  | 1   |          | *FRONT DOOR STEP GARNISH RH           | Scratched     | 415.44 FL   | *415.44 FL   |
| 34  | 1   |          | *FRONT DOOR FRAME RUBBER RH           | Necessary     | 222.83 FL   | *222.83 FL   |
| 35  | 1   |          | *FRONT FENDER WHEEL ARCH GARNISH RH   | Not Necessary | 68.04 FL    | *- FL        |
| 36  | 1   |          | *DASHBOARD                            | Deformed      | 740.19 FL   | *740.19 FL   |
| 37  | 1   |          | *DASHBOARD REINFORCEMENT              | Bent          | 580.49 FL   | *580.49 FL   |
| 38  | 1   |          | *METER ASSY                           | Cracked       | 1,380.69 FL | *1,380.69 FL |
| 39  | 1   |          | *METER TOP GARNISH                    | Cracked       | 220.69 FL   | *220.69 FL   |
| 40  | 1   |          | *STEERING WHEEL INNER COVER           | Cut           | 155.60 FL   | *155.60 FL   |
| 41  | 1   |          | *STEERING WHEEL OUTER COVER           | Cut           | 177.90 FL   | *177.90 FL   |
| 42  | 1   |          | *CABIN MOUNTING                       | Cracked       | 480.50 FL   | *480.50 FL   |
| 43  | 1   |          | *BRAKE BOOSTER PUMP                   | Bent          | 1,845.78 FL | *1,845.78 FL |
| 44  | 1   |          | *BRAKE OIL RESERVOIR                  | Cracked       | 245.64 FL   | *245.64 FL   |
| 45  | 1   |          | *ERP BRACKET                          | Necessary     | 26.00 FS    | *26.00 FS    |

Report was unsubmitted during this print-out.

10/25/21, 11:48 AM

Adjuster Report

| No.                                                | Qty | Part No. | Particulars     | Condition | Repairer's | Amount    |
|----------------------------------------------------|-----|----------|-----------------|-----------|------------|-----------|
| 46                                                 | 1   |          | *FRONT NO PLATE | Bent      | 30.00 FS   | *30.00 FS |
| 47                                                 | 1   |          | *BRAKE OIL      | Necessary | 60.00 FS   | *40.00 FS |
| F=Franchise part. S=SpcNett. L=ListItemDisc.       |     |          |                 |           |            |           |
| Sub Total (S\$)                                    |     |          |                 |           | 20,075.89  | 17,762.25 |
| - List Item Discount on L Items 25.00/25.00% (S\$) |     |          |                 |           | 4,989.97   | 4,416.56  |
| Total Parts (S\$)                                  |     |          |                 |           | 15,085.92  | 13,345.69 |
| Report was unsubmitted during this print-out.      |     |          |                 |           |            |           |

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                            | Particulars                                 | Lab.Type | Repairer's      | Amount          |
|-------------------------------|---------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>           |                                             |          |                 |                 |
| 1                             | TO REMOVE AND RENEW FRONT WINDSCREEN GLASS  | New      | 120.00          | 120.00          |
| 2                             | TO DISMANTLE AND REFIX DASHBOARD FITTING    | New      | 300.00          | 150.00          |
| 3                             | TO TRANSFER DOOR FITTING                    | New      | 100.00          | 60.00           |
| 4                             | TO REMOVE ROOF LINING,CUSHION SEAT & CARPET | New      | 120.00          | 60.00           |
| 5                             | TO TOP-UP AIR-CON GAS                       | New      | 120.00          | 0.00            |
| 6                             | TO CHECK WIRING FUNCTION                    | New      | 50.00           | 30.00           |
| 7                             | LABOUR CHARGES                              | New      | 1,800.00        | 1,400.00        |
| 8                             | TO PUTTY AND SPRAY PAINTING CHARGES         | New      | 1,200.00        | 1,000.00        |
| <b>Gross Labour Cost (\$)</b> |                                             |          | <b>3,810.00</b> | <b>2,820.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >