

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI21010247/VUF3N2**Date:** 19/10/2021REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MQ000087
<b>Claimant Vehicle No :</b>	SH7921D	<b>Insured Vehicle No :</b>	SNC3388E
Date of Loss:	04/10/2021	Nature of Claim:	TP
		Claim No:	M2104625

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SH7921D</b>	Engine No:	G4LEKU417510
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVLU192135
Reg. Date:	28/01/2021 (Man. Year: 2019)	Odometer:	100423 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,596.44	1,087.00	509.44	31.91
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,130.00	900.00	230.00	20.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,737.44</b>	<b>1,998.00</b>	<b>739.44</b>	<b>27.01</b>
<b>+ GST 7.00/7.00% (S\$)</b>	191.62	139.86	51.76	27.01
<b>Nett Amount (S\$)</b>	<b>2,929.06</b>	<b>2,137.86</b>	<b>791.20</b>	<b>27.01</b>

INSPECTION

Date of Assignment:	05/10/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	04/10/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

**Adjuster:** Thevan Thomas Karthikesavan**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 16 Oct 2021)

**Parts:** 192      HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SH7921D)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER ASSY	Cut	459.40 FL	-	*459.40 FL
2	1		*REAR BUMPER CENTRE MOULDING	Scratched	451.25 FL	-	*451.25 FL
3	1		*REAR BUMPER BEAM	Serviceable	394.80 FL	-	*- FL
4	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
5	1		*REAR BUMPER LOWER MOULDING	Distorted	155.00 FL	-	*155.00 FL
6	1		*REAR FOG LAMP	Serviceable	201.50 FL	-	*- FL
7	1		*ANTENNA - SMARTKEY	Serviceable	40.50 FL	-	*- FL
8	1		*REAR NUMBER PLATE	Cracked	50.00 F	-	*50.00 F
9	1		*BOOTLID EMBLEM - H	Necessary	28.00 FL	-	*28.00 FL
10	1		*BOOTLID EMBLEM - IONIQ	Necessary	31.30 FL	-	*31.30 FL
11	1		*BOOTLID EMBLEM - HYBRID	Necessary	24.30 FL	-	*24.30 FL
12	1		*BOOTLID COMFORT LOGO	Necessary	30.00 F	-	*30.00 FS
13	1		*BOOTLID TEL.NOS. LOGO	Necessary	30.00 F	-	*30.00 FS
14	1		*BOOTLID APPS LOGO	Necessary	40.00 F	-	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,958.05</b>	<b>1,321.25</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	361.61	234.25
<b>Total Parts (\$\$)</b>	<b>1,596.44</b>	<b>1,087.00</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT	New	600.00	500.00
3	CHECK WIRING	New	50.00	20.00
4	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
Gross Labour Cost (\$\$)			1,130.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >