

Our Job Ref No 305489207

Date : 07/10/21

ENGINEERING
ComfortDaiGin Engineering Pte Ltd
59 Loyang Drive Singapore 608969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : THEVAN
: SH 7921D


Fax :

DOA: 04/10/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO --- SNC3388E
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$1,087.00
 - (b) Labour Charges \$911.00
 - Total for Part-By-Part Repair Cost** **\$1,998.00**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost _____
3. Estimated normal period for repairs: 2 working days
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : JUMANI
Tel : 6214 8315
Fax : 65468156

Signature : 
Name : THEVAN
Date : 15/10/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	7.49 / 2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305489207
 REGN NO : SH 7921D
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 28.01.2021
 DATE/TIME IN : 04.10.2021 10:05
 ACCIDENT DATE : 04.10.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	28-01-0104-2029-A	VEHICLE NUMBER PLATE REAR	1	N	50.00	0.00	50.00
0002	04-01-0104-2282-G	COVER-RR BUMPER#	1		459.40	20.00	367.52
0003	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1		451.25	20.00	361.00
0004	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10	L	22.00	20.00	17.60
0005	04-01-0104-2545-G	MOULDING-REAR BUMPER LWR	1		155.00	20.00	124.00
0006	04-01-0104-2270-G	EMBLEM-HYBRID	1		24.30	20.00	19.44
0007	04-01-0104-2271-G	EMBLEM-IONIQ	1		31.30	20.00	25.04
0008	04-01-0104-2175-G	SYMBOL MARK-H	1		28.00	20.00	22.40
0009	28-01-0103-0005-A	REAR BOOT LOGO CTPL	1	N	30.00	2.00-	30.00
0010	28-01-0103-0006-A	REAR BOOT TEL NUMBER CTPL	1	N	30.00	0.20	30.00
0011	28-01-9999-2025-A	APP LOGO REAR BONNET CTPL	1	N	40.00	0.02-	40.00

SUB-TOTAL : 1,087.00

JOB NATURE

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305489207
REGN NO : SH 7921D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 28.01.2021
DATE/TIME IN : 04.10.2021 10:0
ACCIDENT DATE : 04.10.2021

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0000 PB	PANEL BEATING (SH 7921d)	350.00				
0001 SP	SPRAYPAINT CHARGE	500.00				
0002 17-01	CHECK ALL LIGHTING	20.00				
0003 L	REMOVE/REFIX REVERSE SENSOR	30.00				
0004 L	MERIMEN FEE	11.00				
SUB-TOTAL :						911.00

TOTAL : 1,998.00

Jumani

MVA NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 04 Oct 2021)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue: Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SH7921D/04/10/2021 12:11 ✓**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER ASSY	20.00	0.00	*459.40 FL ✓/cut
2	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	*451.25 FL ✓/scr
3	1		*REAR BUMPER BEAM	20.00	0.00	*394.80 FL ✓/XSC
4	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL ✓/MCC
5	1		*REAR BUMPER LOWER MOULDING	20.00	0.00	*155.00 FL ✓/DPS
6	1		*REAR FOG LAMP	20.00	0.00	*201.50 FL ✓/SVC
7	1		*ANTENNA - SMARTKEY	20.00	0.00	*40.50 FL ✓/SVC
8	1		*REAR NUMBER PLATE	0.00	0.00	*50.00 F ✓/CRA
9	1		*BOOTLID EMBLEM - H	20.00	0.00	*28.00 FL ✓/MCC
10	1		*BOOTLID EMBLEM - IONIQ	20.00	0.00	*31.30 FL ✓/MCC
11	1		*BOOTLID EMBLEM - HYBRID	20.00	0.00	*24.30 FL ✓/MCC
12	1		*BOOTLID COMFORT LOGO	0.00	0.00	*30.00 F ✓/MCC
13	1		*BOOTLID TEL.NOS. LOGO	0.00	0.00	*30.00 F ✓/MCC
14	1		*BOOTLID APPS LOGO	0.00	0.00	*40.00 F ✓/MCC

F=Franchise part. L=List/ItemDisc.

Sub Total (\$\$)	1,958.05
- List Item Discount on L Items (\$\$)	361.61
Total Parts (\$\$)	1,596.44

ComfortDelGro Engineering Pte Ltd/SH7921D/04/10/2021 12:11. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	400.00 350
2	SPRAYPAINT	New	600.00 500
3	CHECK WIRING	New	50.00 20
4	REMOVE/REFIX REVERSE SENSOR	New	80.00 30
Gross Labour Cost (S\$)			1,130.00

ComfortDelGro Engineering Pte Ltd/SH7921D/04/10/2021 12:11. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thuan@LkhAuto.com
82235769
4/10/19 1630
P/P bfor paint photo
WP 2clays

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: