

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21010249/UEA3Q2**Date:** 07/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210110889
Claimant Vehicle No :	SLV3351J	Insured Vehicle No :	SNB8879C
Date of Loss:	01/10/2021	Nature of Claim:	TP
		Claim No:	8392115880SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV3351J	Engine No:	D4FDHH109807
Make & Model:	KIA CARENS, 1.7 D DCT 5DR FWD (A)	Chassis No:	KNAHU815VJ7192911
Reg. Date:	28/12/2017 (Man. Year: 2017)	Odometer:	355717 km
Colour:	Red		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Grenlander 6 mm	Rear Left Side:	Grenlander 6 mm
Front Right Side:	Grenlander 6 mm	Rear Right Side:	Grenlander 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,368.50	1,604.40	764.10	32.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	1,280.00	820.00	39.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,468.50	2,884.40	1,584.10	35.45
Approved Total (Overridden) (\$\$)		2,300.00		
(\$\$)	4,468.50	2,300.00	2,168.50	48.53
+ GST 7.00/7.00% (\$\$)	312.80	161.00	151.80	48.53
Nett Amount (\$\$)	4,781.30	2,461.00	2,320.30	48.53
+ Loss of Use (3.0 x S\$70.62/day) (\$\$)		211.86		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		2,674.86		

INSPECTION

Date of Assignment:	05/10/2021		
Date Inspected:	05/10/2021	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S REAR DOOR	Dented / Bent	842.00 FL	*842.00 FL
2	1		*O/S REAR DOOR TOP MOULDING	Not Necessary	125.00 FL	*- FL
3	1		*O/S REAR DOOR WEATHERSTRIP	Not Necessary	115.00 FL	*- FL
4	1		*O/S REAR DOOR POWER WINDOW MOTOR	Not Necessary	179.00 FL	*- FL
5	1		*O/S REAR DOOR POWER WINDOW MOTOR GEAR	Not Necessary	200.00 FL	*- FL
6	1		*O/S FRONT DOOR	Dented	914.00 FL	*914.00 FL
7	1		*O/S FRONT DOOR TOP MOULDING	Not Necessary	125.00 FL	*- FL
8	1		*O/S FRONT DOOR WEATHERSTRIP	Not Necessary	105.00 FL	*- FL
9	1		*SET O/S REAR DOOR FRAME STICKER	Necessary	12.00 FS	*12.00 FS
10	1		*SET O/S FRONT DOOR FRAME STICKER	Necessary	12.00 FS	*12.00 FS
					Sub Total (\$\$)	2,629.00 1,780.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	260.50 175.60
					Total Parts (\$\$)	2,368.50 1,604.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER OF DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST	New	200.00	120.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	150.00	60.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	100.00	0.00
4	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	750.00	300.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	900.00	800.00
Gross Labour Cost (S\$)			2,100.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >