

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 5128C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE (CONSISTENT)	BADLY DENTED	1,284.20	1,047.00
1	TAILGATE INNER LOCK (CONSISTENT)	SHORTED	203.60	202.20
1	TAILLAMP O/S (CONSISTENT)	CRACKED	283.60	205.70
1	"RS" EMBLEM (CONSISTENT)	NECESSARY	48.30	48.30
1	I-VTEC EMBLEM (CONSISTENT)	NECESSARY	69.50	38.00
1	MOBILIO EMBLEM (CONSISTENT)	NECESSARY	74.30	45.00
1	TAILGATE W/STRIP (CONSISTENT)	TWISTED	213.40	73.80
1	REAR BUMPER (CONSISTENT)	DENTED / TORN	463.70	463.70
1	REAR BUMPER CHROME LOWER (CONSISTENT)	SCRATCHED	138.00	138.00
1	REAR BUMPER REFLECTOR (CONSISTENT)	NOT NECESSARY	78.30	-
1	END PANEL (CONSISTENT)	DENTED	314.70	314.70
1	END PANEL TOP GARNISH (CONSISTENT)	TWISTED	68.00	68.00
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	65.00	65.00
1	REAR WINDSCREEN SEALANT (CONSISTENT)	NECESSARY	45.00	45.00
1	SET REVERSE SENSOR (CONSISTENT)	SERVICEABLE	280.00	-
1	REAR BUMPER SPONGE O/S (CONSISTENT)	TORN	85.00	85.00
	LESS 20% DISCOUNT		-742.92	-567.88
			2,971.68	2,271.52
	<u>LABOUR</u>			
	TO REMOVE, REFIT REAR WINDSCREEN.		200.00	120.00
	TO REMOVE, REPLACE REVERSE SENSOR.		80.00	50.00
	TO REMOVE, REPLACE TAILGATE & END PANEL & REAR BUMPER.		850.00	600.00
	TO SPRAY PAINTING.		780.00	750.00
			1,910.00	1,520.00
	GRAND TOTAL		4,881.68	3,791.52

Report Ref No. CS/ASM21010252/Uvy3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/ASM21010252/Uvy3e2

CHUA KANG SENG

Licensed Appraiser