

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/III21009366/GQF3E2-1

**Date:** 25/10/2021

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447  
**Claimant Vehicle No :** SMP5637S **Insured Vehicle No :** SLN6104D  
Date of Loss: 05/09/2021 Nature of Claim: TP Claim No: MFL2021D0003873

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP5637S**  
Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A) Engine No: LEB7109269  
Reg. Date: 30/09/2019 (Man. Year: 2018) Chassis No: GP72007377  
Colour: Red Odometer: 237024 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15  
Front Left Side: Firenza 6 mm Rear Left Side: Falken 6 mm  
Front Right Side: Firenza 6 mm Rear Right Side: Falken 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,143.64	4,282.56	1,861.08	30.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	1,710.00	1,230.00	41.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,083.64</b>	<b>5,992.56</b>	<b>3,091.08</b>	<b>34.03</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,800.00</b>		
<b>(S\$)</b>	9,083.64	4,800.00	4,283.64	47.16
<b>+ GST 7.00/7.00% (S\$)</b>	635.85	336.00	299.85	47.16
<b>Nett Amount (S\$)</b>	<b>9,719.49</b>	<b>5,136.00</b>	<b>4,583.49</b>	<b>47.16</b>

### INSPECTION

Date of Assignment: 05/10/2021

Date Inspected: 07/09/2021 Inspected At:

Estimated Period of Repair: 5.0 days

Bluwel Automotive Service Pte Ltd (HQ)  
1 Kaki Bukit Avenue 6, #01-28/37/53/55/56  
Autobay@Kaki Bukit  
Singapore 417883

**Adjuster:** XING GUO QIANG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 25 Oct 2021)	
<b>Parts:</b>	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMP5637S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	95.60 FL	*95.60 FL
2	1		*REAR TAILGATE	Damaged	1,219.00 FL	*986.90 FL
3	2		*REAR TAILGATE DAMPERS	Serviceable	330.00 FL	*- FL
4	1		*REAR TAILGATE INNER BOARD	Damaged	320.00 FL	*320.00 FL
5	1		*REAR TAILGATE LAMPS	N/S Damaged	828.00 FL	*414.00 FL
6	1		*REAR TAILGATE LOCK	Damaged	126.50 FL	*126.50 FL
7	1		*REAR TAILGATE OUTER CHROME MOULDING	Damaged	383.00 FL	*383.00 FL
8	1		*REAR TAILGATE RUBBER	Damaged	168.50 FL	*168.50 FL
9	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	69.00 FL	*46.60 FL
10	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	45.00 FL	*45.00 FL
11	1		*REAR TAILLAMPS	N/S Damaged	1,041.00 FL	*520.50 FL
12	1		*REAR END PANEL	Damaged	560.80 FL	*560.80 FL
13	1		*REAR END PANEL INNER GARNISH	Damaged	155.50 FL	*155.50 FL
14	1		*REAR BUMPER	Damaged	1,072.50 FL	*783.70 FL
15	1		*REAR BUMPER REFLECTORS	N/S Damaged	148.20 FL	*74.10 FL
16	2		*REAR BUMPER SIDE RETAINERS	Serviceable	75.00 FL	*- FL
17	1		*REAR BUMPER TOWING COVER	Serviceable	25.00 FL	*- FL
18	1		*REAR BUMPER REFLECTOR COVER	Serviceable	33.20 FL	*- FL
19	1		*REAR SPARE TYRE TOOLS TRAY	Damaged	285.00 FL	*285.00 FL
20	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
21	1		*REAR TAILGATE LOGO	Necessary	50.00 FS	*40.00 FS
22	1		*SET REAR BUMPER CLIP	Necessary	39.00 FS	*30.00 FS
23	1		*REAR NUMBER PLATE	Serviceable	50.00 FS	*- FS
24	1		*SET REAR REVERSE SENSOR	Damaged	320.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,539.80</b>	<b>5,275.70</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,396.16	993.14
<b>Total Parts (\$\$)</b>	<b>6,143.64</b>	<b>4,282.56</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING, HARNESS WIRES, SOCKETS, REPLACE DAMAGED PARTS	New	70.00	30.00
2	TO REMOVE AND REFIT INNER TRIMS, INNER GARNISHES, TO FACILITATE THE REPAIR	New	180.00	60.00
3	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	160.00	40.00
4	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
5	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WIELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,100.00	600.00
6	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	1,100.00	800.00
7	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	150.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,940.00</b>	<b>1,710.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >