

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | Reg. No: 199607198R GST Reg. No. 19-9607198-R | | | | |
|---|--|--|-----------------|-----------------------|--|
| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
| | AUTO & GENERA | L INSURANCE (S) PL | Ref: | CS/AGI21010256/Btf3n2 | |
| | (BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924 | | Date: | 14/10/2021 | |
| | | | Code | : AGI | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SKX 9581Z | Veh. Inspected | SLJ 8492R | |
| | Policy No. | | Coverage (\$) | 0.00 | |
| | Claim No. | C10011945/HA | Excess (\$) | 0.00 | |
| | Assign From | FRAULEINE KHOO | Assign Date | 05/10/2021 | |
| 2. | 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | TOYOTA HARRIER 2.0 | c.c | 1986 | |
| | Engine No. | HIDDEN | Year of Reg. | 2015 | |
| | Chassis No. | ZSU600022224 | Colour | WHITE | |
| | Odometer | 136618 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | SPORTS RIM | |
| | General | GOOD | | | |
| 3. | . Conditions of Tyres | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 235/55 R18 | MICHELIN | 5 mm | |
| | L/H Front Tyre | 235/55 R18 | MICHELIN | 5 mm | |
| | R/H Rear Tyre | 235/55 R18 | MICHELIN | 5 mm | |
| | L/H Rear Tyre | 235/55 R18 | MICHELIN | 5 mm | |
| 4. | Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | . General Information | | | | |
| | Accident Date | 02/10/2021 | Inspection Date | 05/10/2021 | |
| | Survey held at BIFROST AUTO PTE LTD | | | | |
| | | 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875 | | | |
| 5a. | Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | |

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: