

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21010259/BUF3N2**Date:** 07/12/2021REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001776096
Claimant Vehicle No :	GBL1851S	Insured Vehicle No :	YP6306Z
Date of Loss:	30/09/2021	Nature of Claim:	TP
		Claim No:	263490

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBL1851S	Engine No:	20L4EASSLC090106
Make & Model:	MAXUS G10, 1.9 (A)	Chassis No:	LSKG4AL11MA052180
Reg. Date:	30/03/2021 (Man. Year: 2020)	Odometer:	6100 km
Colour:	Grey		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/70R16	Rear Tyre Size:	215/70R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,105.24	5,223.03	10,882.21	67.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,070.00	1,570.00	1,500.00	48.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,175.24	6,793.03	12,382.21	64.57
Approved Total (Overridden) (\$\$)		4,850.00		
(\$\$)	19,175.24	4,850.00	14,325.24	74.71
+ GST 7.00/7.00% (\$\$)	1,342.27	339.50	1,002.77	74.71
Nett Amount (\$\$)	20,517.51	5,189.50	15,328.01	74.71

INSPECTION

Date of Assignment:	05/10/2021	Ms Car Auto Pte Ltd (HQ)
Date Inspected:	07/10/2021 Inspected At:	8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT
Estimated Period of Repair:	6.0 days	Singapore 415875

Adjuster: Lim Teow Guan**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Dec 2021)
Parts:	143	MAXUS G10 1.9 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL1851S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RIGHT DOOR	Repair	1,683.60 FL	*- FL
2	1		*FRONT DOOR RH	Dented	1,982.20 FL	*1,650.00 FL
3	1		*FRONT DOOR RUBBER	Not Damaged	168.40 FL	*- FL
4	2		*FRONT DOOR HINGE RH	Not Damaged	256.40 FL	*- FL
5	1		*FRONT DOOR LOCK	Jammed	381.80 FL	*115.00 FL
6	1		*FRONT DOOR GLASS	Not Damaged	367.20 FL	*- FL
7	1		*FRONT BUMPER	Dented	453.60 FL	*453.60 FL
8	2		*FRONT BUMPER BRACKET L+R	Necessary	138.40 FL	*138.40 FL
9	1		*FRONT BUMPER FOG LAMP GRILLE LH	Not Damaged	171.40 FL	*- FL
10	2		*HEADLAMP GARNISH L+R	No such part	547.00 FL	*- FL
11	1		*FRONT SUPPORT PANEL	Not Damaged	971.20 FL	*- FL
12	1		*FRONT SIDE MIRROR RH	Dented	476.70 FL	*476.70 FL
13	1		*FRONT FENDER COWLING RH	Torn	268.20 FL	*185.00 FL
14	1		*FRONT FENDER RH	Dented	1,100.00 FL	*885.00 FL
15	1		*HEADLAMP RH	Cut	1,600.00 FL	*1,600.00 FL
16	1		*KNUCKLE ARM LH	Not Damaged	464.30 FL	*- FL
17	1		*LOWER ARM LH	Not Damaged	323.20 FL	*- FL
18	1		*UPPER ARM LH	Not Damaged	980.00 FL	*- FL
19	1		*WHEEL HUB LH	Not Damaged	398.00 FL	*- FL
20	1		*WHEEL BEARING L RH	Jammed	233.00 FL	*233.00 FL
21	1		*LOWER ARM BALL JOINT LH	Not Damaged	294.00 FL	*- FL
22	1		*UPPER ARM BALL JOINT LH	Not Damaged	223.00 FL	*- FL
23	1		*FRONT SHOCK ABSORBER LH	Not Damaged	362.00 FL	*- FL
24	1		*FRONT STEERING RACK AND PINION	Not Damaged	3,940.00 FL	*- FL
25	1		*SET FRONT BUMPER	Necessary	50.00 FS	*30.00 FS
26	1		*SET FRONT FENDER INNER COWLING CLIP	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,883.60	5,796.70
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,778.36	573.67
Total Parts (\$\$)	16,105.24	5,223.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R & R ACCIDENT DAMAGE PARTS,CUT/WELD,KNOCK AND REALIGN ACCIDENT AFFECTED AREA	New	1,200.00	800.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	1,200.00	600.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	150.00	0.00
4	CHECK ALIGNMENT	New	180.00	60.00
5	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	New	80.00	0.00
6	TO PRESS FRONT WHEEL BEARING	New	80.00	30.00
7	REMOVE AND REFIX FRONT UNDER CARRIAGE	New	180.00	80.00
Gross Labour Cost (\$)			3,070.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >