

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Katherine Wong

Date: 16 Nov 2021

**Preliminary Advice**

Insured Vehicle No	: YP6306Z		
TP Vehicle No	: GBL1851S	Accident Date	: 30/09/2021
Make	: MAXUS G10	Assignment Date	: 05/10/2021
Date of Inspection	: 07/10/2021	Est. Duration of Repair	: 6
Inspection At	: MS CAR AUTO PTE LTD (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,175.24
Revised Amount	:S\$	6,793.03
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,793.03
Lump Sum Repair	:S\$	5,400.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical for repair
- ( ) The vehicle is not economical for repair
- ( ) Part-by-Part repair
- ( X ) Lump Sum repair
  
- ( X ) The above survey was conducted on a 'without prejudice' basis.  
Please note that the preliminary advice amount (Revised) stated are subject to consistency check, part prices and labour cost.