

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21010261/R1qy3e2	
	8 SHENTON WAY SINGAPORE 0688		Date:	14/10/2021		
	ATTN: KHONG LY	NN		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SMG 4154Y	Veh. Inspected	t	FBJ 517A	
	Policy No.	P2222386	Coverage (\$)		0.00	
	Claim No.	S1M03J0C	Excess (\$)		0.00	
	Assign From	KHONG LYNN	Assign Date		05/10/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	YAMAHA FZ1-S	c.c		998	
	Engine No.	HIDDEN	Year of Reg.		2013	
	Chassis No.	JYARN16D000000881	Colour		WHITE	
	Odometer	58962 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	120/70Z R17	METZELER		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	190/55Z R17	METZELER		4 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
5.	5. General Information					
	Accident Date	09/09/2021	Inspect Date /	Time	05/10/2021 (05:12 PM)	
	Survey held at SPEEDY MOTOR CYCLE SERVICE CENTRE					
	BLK 10 ANG MO KIO IND.PARK 2A #05-21 SINGAPORE 568047					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000					
5b. Estimate Days of Repair						
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM21010261/R1qy3e2

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

DECD And Completed OAF Lines of Associate

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$