

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT | | | | | |
|------------------------------------|---|--|---------------------|-------------------------|--|
| | AXA INSURANCE | PTE LTD | Ref: | CS3/ASM21010262/Vty3e2 | |
| | 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 | | Date: | 20/10/2021 | |
| | ATTN: CHAN KIAN | I CHUAN | Code: | ASM | |
| 1. | Policy Particulars :- (THIRD PARTY CLAIM) | | | | |
| | Insured Veh. | SHC 8677J | Veh. Inspected | PC 4843C | |
| | Policy No. | VFX/P2419138 | Coverage (\$) | 0.00 | |
| | Claim No. | S1M03J6Z | Excess (\$) | 0.00 | |
| | Assign From | CHAN KIAN CHUAN | Assign Date | 05/10/2021 | |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | TOYOTA HIACE DX 3.0 A | c.c | 2982 | |
| | Engine No. | HIDDEN | Year of Reg. | 2016 | |
| | Chassis No. | KDH2010194981 | Colour | SILVER | |
| | Odometer | 224730 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | SPORTS RIM | |
| | General | GOOD | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 195 R15C | MICHELIN | 6 mm | |
| | L/H Front Tyre | 195 R15C | MICHELIN | 6 mm | |
| | R/H Rear Tyre | 195 R15C | MICHELIN | 6 mm | |
| | L/H Rear Tyre | 195 R15C | MICHELIN | 6 mm | |
| 4. | Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/BODY. | | | | |
| 5. | 5. General Information | | | | |
| | Accident Date | 01/10/2021 | Inspect Date / Time | 05/10/2021 (04:00 PM) | |
| | Survey held at TEAMWORK GARAGE PTE LTD | | | | |
| | 53 UBI AVENUE 1 #01-24 SINGAPORE 408934. | | | | |
| 5a. | Remarks | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000 | | | | |
| 5b. | 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NOR | ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days | | | |

Report Ref No. CS3/ASM21010262/Vty3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser