

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT MS FIRST CAPITAL INSURANCE LTD CS3/FCI21010263/Vtf3e2 Ref: 36 ROBINSON ROAD #16-01 CITY HOUSE Date: 20/10/2021 SINGAPORE 068877 Code: FCI2 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **GBC 6467H GBF 6094J** Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. D21002781MFCV Excess (\$) 0.00 AINI BINTE **Assign Date** 05/10/2021 Assign From 2. **Vehicle Particulars & Condition** TOYOTA DYNA Make & Model 2982 C.C HIDDEN 2016 Engine No. Year of Reg. KDY2318025908 SILVER Chassis No. Colour Odometer 54429 KM Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195 R15C PRACTICAL MAX 5 mm PRACTICAL MAX L/H Front Tyre 195 R15C 5 mm 155 R13C PRACTICAL MAX R/H Rear Tyre 5 mm PRACTICAL MAX 5 mm L/H Rear Tyre 155 R13C 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. 5. **General Information** 30/09/2021 05/10/2021 (05:00 PM) Inspect Date / Time Accident Date HALLAND MOTOR SERVICE Survey held at NO.1 KAKI BUKIT AVE 6 #02-24 SINGAPORE 417883 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$47,000.00

Report Ref No. CS3/FCI21010263/Vtf3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

1

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser