

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010264/UTY3N2**Date:** 02/11/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00196522000

Claimant Vehicle No : SGW2283H **Insured Vehicle No :** SKB9711G

Date of Loss: 29/09/2021 Nature of Claim: TP Claim No: SNM21D205563/C2/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGW2283H**

Make & Model: TOYOTA ESTIMA, 2.4 (A) Engine No: 2AZC197756

Reg. Date: 10/07/2007 (Man. Year: 2007) Chassis No: ACR500035240

Colour: Silver Odometer: 283993 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/55R17 Rear Tyre Size: 225/55R17

Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,034.75	4,750.08	6,284.67	56.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,440.00	1,850.00	1,590.00	46.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,474.75	6,600.08	7,874.67	54.40
Approved Total (Overridden) (S\$)		5,200.00		
Nett Amount (S\$)	14,474.75	5,200.00	9,274.75	64.08

INSPECTION

Date of Assignment: 26/10/2021

Date Inspected: 08/10/2021 Inspected At: BLK 10 KAKI BUKIT ROAD 2
#01-05 FIRST EAST CENTRE
SINGAPORE 417868
REPAIRER: PROFI AUTOMOTIVE

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 29 Oct 2021)
Parts: M1-MPV	TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGW2283H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR SLIDING DOOR RH	Badly Dented	2,596.00 FL	*1,816.21 FL
2	1		*REAR SLIDING DOOR TAPE-UPPER RH	Necessary	96.00 FL	*96.00 FL
3	1		*REAR SLIDING DOOR TAPE-LOWER RH	Necessary	65.00 FL	*65.00 FL
4	1		*REAR SLIDING DOOR LOCK RH	Not Necessary	455.00 FL	*- FL
5	1		*REAR SLIDING DOOR REGULATOR RH	Bent/Jammed	653.00 FL	*492.30 FL
6	1		*REAR SLIDING DOOR INNER TRIM RH	Not Necessary	655.00 FL	*- FL
7	1		*REAR BUMPER	Cut/Torn	943.00 FL	*645.10 FL
8	1		*REAR BUMPER RETAINER	Necessary	112.00 FL	*85.50 FL
9	1		*REAR LOWER ARM RH	Not Necessary	521.00 FL	*- FL
10	1		*REAR KNUCKLE ARM RH	Not Necessary	442.00 FL	*- FL
11	1		*REAR KNUCKLE BEARING RH	Not Necessary	213.00 FL	*- FL
12	1		*REAR SHOCK ABSORBER RH	Not Necessary	657.00 FL	*- FL
13	1		*REAR FENDER RH	Repair	2,545.00 FL	*- FL
14	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
15	1		*SET REAR DOOR INNER CLIP	Necessary	30.00 FS	*30.00 FS
16	1		*REAR RIM O/S	Cut	800.00 FS	*680.00 FS
17	1		*REAR TYRE O/S	Serviceable	400.00 FS	*- FS
18	1		*REAR WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
19	1		*JOINT SEALANT	Not Necessary	120.00 FS	*- FS
20	1		*(BT) BRAKE FLUID	Not Necessary	60.00 FS	*- FS
21	1		*REAR DOOR LOWER GARNISH (KENS STYLE) RH	Cut	600.00 FS	*600.00 FS
22	1		*REAR MUD GUARD (KENS STYLE) RH	Cut	200.00 FS	*100.00 FS
23	1		*REAR BUMPER LOWER SPOILER (KENS STYLE)	Cut	1,200.00 FS	*900.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	13,523.00	5,550.11
- List Item Discount on L Items 25.00/25.00% (S\$)	2,488.25	800.03
Total Parts (S\$)	11,034.75	4,750.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND LIGHTNING SYSTEM	New	120.00	20.00
2	COMPUTERISED REAR WHEEL ALIGNMENT	New	180.00	60.00
3	REMOVE AND REFIT REAR LINING,TRIM AND GARNISH	New	200.00	80.00
4	REMOVE AND REFIT REAR QUARTER GLASS RH	New	120.00	0.00
5	REMOVE AND REFIT REAR REVERSE SENSOR	New	120.00	50.00
6	TRANSFER PARTS,ATTACHMENT FROM OLD DOOR TO NEW	New	250.00	60.00
7	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS	New	300.00	0.00
8	PANEL BEATING AND RENEW DAMAGE PARTS ON AFFECTED AREAS	New	800.00	550.00
9	SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	1,000.00
10	APPLY ANTI RUST ON EFFECTED PARTS	New	150.00	30.00
Gross Labour Cost (\$)			3,440.00	1,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >