

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### **TAX INVOICE**

LONPAC INSURANCE BHD INV No. AC2302436

300 BEACH ROAD INV Date 18/04/2023

#17-04/07 THE CONCOURSE Reference CC4/LPC21010265/Kya3q2 SINGAPORE 199555

Code LPC2

#### PROFESSIONAL SERVICE FEE

Vehicle No. SMX 3266A

Insured Veh. GBF 6665L

Claim No. 21/21/VC00/025009

Policy No. Z/21/VC00/109274

Accident Date 04/10/2021

Inspection Date 05/10/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 

**LKM** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile					
	LONPAC INSURAI	NCE BHD	Ref:	CC4/LPC21010265/Kya3q2		
	300 BEACH ROAD #17-04/07 THE CC	) NCOURSESINGAPORE 199555	Date	18/04/2023		
			Code	: LPC2		
1.		Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBF 6665L	Veh. Inspected	SMX 3266A		
	Policy No.	Z/21/VC00/109274	Coverage (\$)	0.00		
	Claim No.	21/21/21/VC00/025009	Excess (\$)	0.00		
	Assign From	ENG HUEY NI	Assign Date	05/10/2021		
2.		Vehicle Partic	culars & Condition			
	Make & Model	TOYOTA PRIUS (A)	c.c	1798		
	Engine No.	HIDDEN	Year of Reg.	2021		
	Chassis No.	JTDKB3FU903092514	Colour	METALLIC RED		
	Odometer	67571 KM	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM		
	General	GOOD				
3.		Conditi	ons of Tyres			
		Size	Make	Balance		
	R/H Front Tyre	195/65 R15	SAILUN	9 mm		
	L/H Front Tyre	195/65 R15	SAILUN	9 mm		
	R/H Rear Tyre	195/65 R15	DUNLOP	2 mm		
	L/H Rear Tyre	195/65 R15	DUNLOP	2 mm		
4.		Description	on of Damages			
	THE VEHICLE SU	STAINED DAMAGES AT THE RE	AR PORTION.			
	DAMAGES SEE D	ETAILS.				
5.		Genera	I Information			
	Accident Date	04/10/2021	Inspection Date	05/10/2021		
	Survey held at	TRANS-CAB AUTO SERVICES	PTE LTD			
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111				
5a.		R	emarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate	Days of Repair			
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	2 Wo	rking Days		



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMX 3266A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER ,REAR BUMPER	BUCKLED / DENTED	485.60	485.60
1	REINFORCEMENT SUB-ASSY ,REAR BUMPER	BENT	332.70	332.70
1	GUARD ,REAR BUMPER ,CENTER	DENTED / CUT	374.50	374.50
1	COVER ,REAR BUMPER ,LOWER	DENTED	22.00	22.00
1	RETAINER ,REAR BUMPER SIDE ,LH	NO SUCH PARTS	132.60	-
1	PANEL SUB-ASSY ,BODY LOWER BACK	TO REPAIR SEE LABOUR	651.00	-
1	COVER ,DECK TRIM ,REAR	SERVICEABLE	126.70	-
1	RETAINER ,REAR BUMPER SIDE ,RH	NO SUCH PARTS	132.60	-
	LESS 25% DISCOUNT		-564.43	-303.70
			1,693.27	911.10
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	85.00	50.00
1	BUMPER CENTRE GUARD CLIP (SN)	NOT NECESSARY	80.00	-
1	REAR BUMPER PROTECTOR (SN)	NECESSARY	180.00	40.00
1	REAR BUMPER RETAINER CLIP (SN)	NOT NECESSARY	75.00	-
			1,120.00	90.00
	<u>LABOUR</u>			
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS .	NOT NECESSARY	240.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY ,BODY LOWER BACK .		3,000.00	200.00
	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENT TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,600.00	220.00

Report Ref No. CC4/LPC21010265/Kya3q2



**RECOMMENDED COST OF REPAIRS** 

### **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

1,471.10

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE AND REFIT REAR BIG & SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	300.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR .		170.00	50.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	-
			6,240.00	470.00
	GRAND TOTAL		9,053.27	1,471.10

Report Ref No. CC4/LPC21010265/Kya3q2

KONG SENG CHEONG

**Licensed Appraiser** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SMX 3266A

#### **INSPECTION**
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SMX 3266A

**RE-INSPECTION** 



