

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21010266/BUF3E2

Date: 07/12/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/21-514486-WTT
Claimant Vehicle No :	SLQ3705Z	Insured Vehicle No :	FBJ5712U
Date of Loss:	02/10/2021	Nature of Claim:	TP
		Claim No:	MSC/V/21-000438

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ3705Z		
Make & Model:	KIA SORENTO, 2.2 D CRDI 4WD S/R (A)	Engine No:	D4HBHH318113
Reg. Date:	06/07/2017 (Man. Year: 2017)	Chassis No:	KNAPH81BSH5353761
Colour:	White	Odometer:	159255 km
Engine Capacity:	2199 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Catchfors 5 mm	Rear Left Side:	Catchfors 5 mm
Front Right Side:	Catchfors 5 mm	Rear Right Side:	Catchfors 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,144.60	8,578.93	3,565.67	29.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,030.00	1,460.00	1,570.00	51.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,174.60	10,038.93	5,135.67	33.84
Approved Total (Overridden) (S\$)		8,000.00		
(S\$)	15,174.60	8,000.00	7,174.60	47.28
+ GST 7.00/7.00% (S\$)	1,062.22	560.00	502.22	47.28
Nett Amount (S\$)	16,236.82	8,560.00	7,676.82	47.28

INSPECTION

Date of Assignment:	05/10/2021	
Date Inspected:	07/10/2021 Inspected At:	Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	8.0 days	

Adjuster: Lim Teow Guan

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Dec 2021)
Parts:	M1-SUV	KIA SORENTO 2.2 D CRDI 4WD S/R (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ3705Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	657.00 FL	*645.00 FL
2	1		*FRONT BUMPER RH SIDE RETAINER	Necessary	22.00 FL	*22.00 FL
3	1		*FRONT BUMPER LH SIDE RETAINER	Necessary	22.00 FL	*22.00 FL
4	1		*FRONT BUMPER NUMBER PLATE HOLDER	Necessary	48.00 FL	*20.00 FL
5	1		*FRONT BUMPER RH FOG LAMP ASSY	Missing	202.00 FL	*202.00 FL
6	1		*FRONT BUMPER RH FOG LAMP COVER	Missing	122.00 FL	*122.00 FL
7	1		*FRONT BUMPER LH FOG LAMP ASSY	Not Damaged	202.00 FL	*- FL
8	1		*FRONT BUMPER LH FOG LAMP COVER	Not Damaged	122.00 FL	*- FL
9	1		*FRONT BUMPER LOWER GARNISH	Broken	301.00 FL	*301.00 FL
10	1		*FRONT BUMPER LOWER GARNISH CENTRE COVER	Broken	178.00 FL	*178.00 FL
11	1		*FRONT BUMPER RH SIDE PARKING SENSOR	Short Circuit	158.00 FL	*158.00 FL
12	1		*FRONT BUMPER RH PARKING SENSOR	Short Circuit	158.00 FL	*158.00 FL
13	1		*FRONT BUMPER RH CENTRE PARKING SENSOR	Short Circuit	158.00 FL	*158.00 FL
14	1		*FRONT BUMPER LH CENTRE PARKING SENSOR	Not Damaged	158.00 FL	*- FL
15	1		*FRONT BUMPER LH PARKING SENSOR	Not Damaged	158.00 FL	*- FL
16	1		*FRONT BUMPER LH SIDE PARKING SENSOR	Not Damaged	158.00 FL	*- FL
17	6		*FRONT BUMPER PARKING SENSOR HOLDERS	Necessary	90.00 FL	*90.00 FL
18	1		*FRONT BUMPER PARKING SENSOR WIRE HARNESS	Cut	242.00 FL	*242.00 FL
19	1		*FRONT BUMPER INNER SPONGE	Broken	67.00 FL	*67.00 FL
20	1		*FRONT BUMPER LOWER CENTRE GRILLE	Broken	158.00 FL	*85.00 FL
21	1		*FRONT RH FENDER	Dented	415.00 FL	*415.00 FL
22	1		*FRONT RH FENDER ARCH MOULDING	Cut	155.00 FL	*155.00 FL
23	1		*FRONT RH FENDER SPLASH SHIELD	Torn	76.00 FL	*76.00 FL
24	1		*FRONT LH FENDER ARCH MOULDING	Not Damaged	155.00 FL	*- FL
25	1		*FRONT LH FENDER SPLASH SHIELD	Not Damaged	76.00 FL	*- FL
26	1		*RH HEADLAMP ASSY	Cut	1,694.00 FL	*1,694.00 FL
27	1		*RH HEADLAMP WASHER NOZZLE COVER	Missing	26.00 FL	*26.00 FL
28	1		*RH HEADLAMP WASHER NOZZLE	Broken	152.00 FL	*152.00 FL
29	1		*LH HEADLAMP ASSY	Broken	1,694.00 FL	*1,694.00 FL
30	1		*LH HEADLAMP WASHER NOZZLE COVER	Broken	26.00 FL	*26.00 FL
31	1		*LH HEADLAMP WASHER NOZZLE	Broken	152.00 FL	*152.00 FL
32	1		*FRONT CHROME GRILLE	Dislodged	618.00 FL	*618.00 FL
33	1		*FRONT CHROME GRILLE EMBLEM	Necessary	78.00 FL	*78.00 FL
34	1		*WIPER TANK	Broken	197.00 FL	*145.70 FL
35	1		*WIPER TANK MOTOR	Not Damaged	94.00 FL	*- FL
36	1		*SUPPORT PANEL	Broken	578.00 FL	*578.00 FL
37	1		*FRONT RH WHEEL BEARING	Not Damaged	215.00 FL	*- FL
38	1		*FRONT RH SHOCK ABSORBER	Not Damaged	302.00 FL	*- FL
39	1		*FRONT RH LOWER ARM	Not Damaged	404.00 FL	*- FL
40	1		*FRONT RH LOWER ARM BALL JOINT	Not Damaged	48.00 FL	*- FL
41	1		*FRONT RH KNUCKLE ARM (NPA)	Not Damaged	0.00 FL	*- FL
42	1		*BONNET	Dented	1,158.00 FL	*1,158.00 FL
43	1		*FRONT NUMBER PLATE	Bent	70.00 FS	*25.00 FS
44	1		*SET FRONT BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
45	1		*SET FRONT RH FENDER SPLASH SHIELD CLIPS	Necessary	60.00 FS	*30.00 FS
46	1		*SET FRONT LH FENDER SPLASH SHIELD CLIPS	Not Damaged	60.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS
48	1		*FRONT RH SPORT RIM	Not Damaged	950.00 FS	*- FS
49	1		*FRONT RH TYRE	Not Damaged	350.00 FS	*- FS
50	1		*BRAKE FLUID (NPA)	Not Necessary	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,314.00	9,522.70
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,169.40	943.77
Total Parts (\$\$)	12,144.60	8,578.93

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,000.00	800.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,000.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	30.00	0.00
5	REMOVE AND REINSTALL AIRCON CONDENSER AND PIPES TO ASSIST REPAIR. TO REFILL AIRCON GAS	New	220.00	0.00
6	REMOVE AND REINSTALL RADIATOR ASSY, HOSES AND FAN ASSY TO ASSIST REPAIR. TO REFILL COOLANT	New	220.00	0.00
7	REMOVE AND REPLACE FRONT BUMPER PARKING SENSORS AND WIRE HARNESS TO ASSIST REPAIR	New	100.00	60.00
8	REMOVE AND REPLACE FRONT RH UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	280.00	0.00
9	CONDUCT AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	0.00
Gross Labour Cost (\$\$)			3,030.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >