



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: NG STACEY			Ref: CS/ASM21010267/Auy3e2 Date: 25/11/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	GBG 6044Z	Veh. Inspected	SJJ 145U
	Policy No.		Coverage (\$)	0.00
	Claim No.	S1M03JCK	Excess (\$)	0.00
	Assign From	NG STACEY	Assign Date	05/10/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HONDA STREAM	c.c	1799
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	RN61042052	Colour	RED
	Odometer	163705 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/40 R18	MICHELIN	6 mm
	L/H Front Tyre	225/40 R18	MICHELIN	6 mm
	R/H Rear Tyre	225/40 R18	MICHELIN	6 mm
	L/H Rear Tyre	225/40 R18	MICHELIN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	04/10/2021	Inspection Date	06/10/2021
	Survey held at	1 KAKI BUKIT AVENUE 6 #02-14 AUTOBAY		
	Repairer	AUTOMOBILE HUB ENTERPRISE		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	