

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010269/BPA3Q2**Date:** 08/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070142956
Claimant Vehicle No :	SMX4694R	Insured Vehicle No :	SMV7127C
Date of Loss:	30/09/2021	Nature of Claim:	TP
		Claim No:	8852501329SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX4694R	Engine No:	2ZR2C66429
Make & Model:	TOYOTA C-HR HYBRID, 1.8 S CVT (A)	Chassis No:	ZYX102163551
Reg. Date:	14/01/2021 (Man. Year: 2018)	Odometer:	109508 km
Colour:	Silver		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Davanti 4 mm	Rear Left Side:	Davanti 4 mm
Front Right Side:	Davanti 4 mm	Rear Right Side:	Davanti 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,405.37	4,298.23	7,107.14	62.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,600.00	1,680.00	2,920.00	63.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,005.37	5,978.23	10,027.14	62.65
Approved Total (Overridden) (S\$)		5,950.00		
(S\$)	16,005.37	5,950.00	10,055.37	62.82
+ GST 7.00/7.00% (S\$)	1,120.38	416.50	703.88	62.83
Nett Amount (S\$)	17,125.75	6,366.50	10,759.25	62.82
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,073.95		

INSPECTION

Date of Assignment:	05/10/2021	Team Autopro Pte Ltd - Sin Ming (HQ)
Date Inspected:	05/10/2021 Inspected At:	160 SIN MING DRIVE #02-12 SIN MING
		AUTOCITY
		Singapore 575722
Estimated Period of Repair:	6.0 days	

Adjuster: Lim Teow Guan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,445.50 FL	*1,112.45 FL
2	1		*TAILGATE LOGO	Necessary	84.50 FL	*60.20 FL
3	1		*TAILGATE EMBLEM CHR	Necessary	129.60 FL	*52.90 FL
4	1		*TAILGATE EMBLEM HYBRID SYNERGY DRIVE	Necessary	106.30 FL	*65.70 FL
5	1		*TAILGATE INNER LOCK	Not Damaged	364.50 FL	*- FL
6	1		*TAILGATE INNER STRIKER	Not Damaged	58.00 FL	*- FL
7	1		*TAILGATE INNER TRIM BOARD	Not Damaged	267.80 FL	*- FL
8	1		*TAILGATE OUTER GARNISH	Broken	978.10 FL	*882.20 FL
9	1		*TAILGATE LAMP	N/S Cut	1,157.80 FL	*454.00 FL
10	1		*TAILGATE WINDSCREEN MOULDING	Necessary	184.60 FL	*184.60 FL
11	1		*TAILGATE ANTENNA SENSOR	Not Damaged	198.30 FL	*- FL
12	1		*REAR BUMPER	Broken	1,124.50 FL	*685.10 FL
13	1		*REAR BUMPER LOWER LID	Broken	465.00 FL	*400.00 FL
14	1		*REAR BUMPER LOWER LID CENTRE GARNISH	Not Damaged	68.00 FL	*- FL
15	1		*REAR BUMPER REINFORCEMENT	Bent	578.90 FL	*322.30 FL
16	2		*REAR BUMPER SIDE RETAINER	Necessary	136.00 FL	*136.00 FL
17	1		*REAR BUMPER TOW COVER	Not Damaged	35.00 FL	*- FL
18	2		*REAR BUMPER REFLECTOR	Not Damaged	436.00 FL	*- FL
19	1		*REAR BUMPER REFLECTOR GARNISH	N/S Broken	270.00 FL	*135.00 FL
20	1		*REAR END PANEL	Repair	789.10 FL	*- FL
21	1		*REAR END PANEL TOP GARNISH	Not Damaged	285.70 FL	*- FL
22	1		*REAR FENDER INNER TRIM BOARD LH	Not Damaged	987.90 FL	*- FL
23	1		*REAR FENDER ARCH GARNISH LH	No such part	295.00 FL	*- FL
24	1		*TAILLAMP	N/S Cut	1,964.40 FL	*585.52 FL
25	1		*TAILLAMP LOWER BRACKET	N/S Broken	250.00 FL	*95.00 FL
26	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
27	1		*TAILGATE SEALANT	Necessary	100.00 FS	*30.00 FS
28	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*20.00 FS
29	1		*TAILGATE OUTER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
30	2		*TAILGATE LAMP CLIPS	Necessary	100.00 FS	*20.00 FS
31	2		*TAILGATE LAMP SEAL	No such part	120.00 FS	*- FS
32	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
33	1		*TAILGATE WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
34	1		*TAILGATE WINDSCREEN PRIMER & CLEANER	Not Necessary	80.00 FS	*- FS
35	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
36	1		*REAR BUMPER LOWER LID CLIPS	Necessary	50.00 FS	*20.00 FS
37	2		*REAR BUMPER REFLECTOR GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
38	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
39	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
40	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
41	1		*REAR FENDER ARCH GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
42	1		*TAILLAMP CLIPS	N/S Necessary	100.00 FS	*20.00 FS
43	1		*TAILLAMP SEAL	N/S Necessary	120.00 FS	*20.00 FS
44	2		*REAR BUMPER REVERSE SENSOR	Scratched	500.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,570.50	5,590.97
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,165.13	1,292.74
Total Parts (\$\$)	11,405.37	4,298.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R TAILGATE COMPONENT	New	150.00	80.00
2	R&R TAILGATE WINDSCREEN	New	250.00	120.00
3	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
4	CHECK WIRING	New	100.00	20.00
5	UPHOLSTERY	New	300.00	0.00
6	DIAGNOSTIC RESET FAULT CODE	New	300.00	0.00
7	PANEL BEATING	New	1,600.00	800.00
8	RUST PROOFING	New	200.00	0.00
9	SPRAY PAINTING	New	1,600.00	600.00
Gross Labour Cost (\$\$)			4,600.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >