

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21010271/ATY3N2**Date:** 08/12/2021**REFERENCE**

Insured/Claimant:	TANG BUCK KIAU	Policy No:	7210019767	
Date of Loss:	02/10/2021	Nature of Claim:	OD	Claim No: 8917984661SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD6572M		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	DEM028524
Reg. Date:	25/02/2021 (Man. Year: 2020)	Chassis No:	WAUZZZF52MA018405
Colour:	White	Odometer:	9553 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$172,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45R17	Rear Tyre Size:	215/45R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,600.94	11,818.96	10,781.98	47.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,372.00	3,022.00	7,350.00	70.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,972.94	14,840.96	18,131.98	54.99
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	32,172.94	14,040.96	18,131.98	56.36
+ GST 7.00/7.00% (S\$)	2,252.11	982.87	1,269.24	56.36
Nett Amount (S\$)	34,425.05	15,023.83	19,401.22	56.36

INSPECTION

Date of Assignment:	05/10/2021		
Date Inspected:	04/10/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,342.00 FS	*1,873.60 FS
2	2		*FRONT BUMPER SECURING STRIP	Missing	71.00 FS	*56.32 FS
3	1		*FRONT BUMPER LOWER GRILLE	Cracked	195.00 FS	*156.40 FS
4	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Cracked	262.00 FS	*209.20 FS
5	1		*FRONT BUMPER SPOILER	Not Necessary	535.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE-RH	Missing	63.00 FS	*50.08 FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	262.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Missing	135.00 FS	*108.00 FS
9	1		*FRONT BUMPER TRIM-RH	Damaged	48.00 FS	*38.00 FS
10	1		*FRONT BUMPER TRIM-CENTER	Not Necessary	114.00 FS	*- FS
11	1		*RADIATOR GRILLE	Cracked	1,694.00 FS	*1,355.20 FS
12	1		*FOAM FILLER PIECE	Not Necessary	146.00 FS	*- FS
13	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	845.00 FS	*- FS
14	1		*FRONT BUMPER BRACKET-RH	Not Necessary	214.00 FS	*- FS
15	1		*FRONT BUMPER GUIDE SECTION-RH	Not Necessary	36.00 FS	*- FS
16	1		*FRONT BUMPER TOP COVER-RH	Not Necessary	127.00 FS	*- FS
17	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
18	1		*A/C STICKER	Not Necessary	8.00 FS	*- FS
19	1		*LOCK CARRIER BRACKET	Cracked	137.00 FS	*109.60 FS
20	1		*LOCK CARRIER SUPPORT BRACKET	Not Necessary	58.00 FS	*- FS
21	1		*HORN-RH	Not Necessary	126.00 FS	*- FS
22	1		*HORN BRACKET-RH	Not Necessary	29.00 FS	*- FS
23	2		*FRONT PARKING AID SENSOR-INNER/OUTER	Outer Missing	243.94 FS	*195.12 FS
24	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	9.00 FS	*- FS
25	1		*FRONT BUMPER WIRING SET	Not Necessary	405.00 FS	*- FS
26	1		*FRONT FENDER-RH	Buckled	1,060.00 FS	*848.00 FS
27	1		*FRONT FENDER ATTACHMENT PARTS-RH	Not Necessary	35.00 FS	*- FS
28	1		*FRONT FENDER BRACE-RH	Bent	118.00 FS	*94.40 FS
29	1		*FRONT FENDER TRIM-RH	Necessary	164.00 FS	*130.80 FS
30	1		*FRONT WHEEL HOUSING LINER-RH	Not Necessary	275.00 FS	*- FS
31	1		*FRONT WHEEL SPOILER-RH	Cracked	169.00 FS	*135.20 FS
32	1		*FRONT WHEEL SPOILER TRIM-RH	Cracked	36.00 FS	*28.56 FS
33	1		*LED HEADLIGHT-RH	Cracked	7,685.00 FS	*6,148.00 FS
34	1		*LIFT CYLINDER-RH	Not Necessary	198.00 FS	*- FS
35	1		*LIFT CYLINDER PIPE-RH	Not Necessary	198.00 FS	*- FS
36	1		*LOCK CARRIER	Not Necessary	1,016.00 FS	*- FS
37	1		*LOCK CARRIER LOWER SUPPORT-RH	Not Necessary	38.00 FS	*- FS
38	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	19.00 FS	*- FS
39	1		*A/C CONDENSOR	Not Necessary	622.00 FS	*- FS
40	1		*AIR CHARGE COOLER	Not Necessary	587.00 FS	*- FS
41	1		*CHARGE AIR COOLER PRESSURE HOSE-RH	Not Necessary	357.00 FS	*- FS
42	1		*RADIATOR	Not Necessary	904.00 FS	*- FS
43	1		*RADIATOR AIR GUIDE-RH	Not Necessary	32.00 FS	*- FS
44	1		*RADIATOR AIR GUIDE-RH	Not Necessary	16.00 FS	*- FS
45	1		*RADIATOR AIR GUIDE-UPPER	Not Necessary	16.00 FS	*- FS
46	1		*RADIATOR AIR GUIDE-LOWER	Not Necessary	22.00 FS	*- FS
47	6		*RADIATOR COOLANT	Not Necessary	267.00 FS	*- FS
48	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
49	1		*SUNDRIES	Necessary	350.00 FS	*34.16 FS
50	1		*FRONT FENDER CLOSING ELEMENT - RH Supplementary	Bent	74.00 FS	*59.04 FS
51	1		*FRONT FENDER BRACKET - RH Supplementary	Bent	35.00 FS	*27.92 FS
52	1		*FRONT FENDER RIVET SET Supplementary	Necessary	33.00 FS	*26.40 FS
53	1		*FRONT FENDER TOP LEDGE COVER - RH OUTER Supplementary	Cracked	16.00 FS	*12.24 FS

Report was unsubmitted during this print-out.

12/8/21, 10:10 AMAdjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*FRONT FENDER TOP LEDGE COVER - RH INNER Supplementary	Cracked	36.00 FS	*28.24 FS
55	1		*HEADLIGHT COVER- RH Supplementary	Cracked	44.00 FS	*34.48 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					22,600.94	11,818.96
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO RENEW AND RENEW AIRCON CONDENSER,CHARGED AIR COOLER AND RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS (R1234)	New	2,000.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER,AND RHS HEADLIGHT.TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.REINSTALL ALL PARTS REMOVED	New	4,800.00	1,000.00
5	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,500.00	1,100.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			10,372.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >