



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 82Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	WINDSCREEN FRT:CENTRE, FOR MB OC500 BUS	CRACKED	6,210.00	6,210.00
1	WINDSCREEN, FRT:R/H, FOR MB OC500 BUS	CRACKED	931.50	931.50
1	MIRROR, VIEW:REAR, ELECTRICAL, RH, MBOC500	CRACKED	1,139.05	1,139.05
	LESS 10% DISCOUNT		-	-828.06
			8,280.55	7,452.49
	<u>SPECIAL NETT ITEMS</u>			
1	PRIMER (SIKA 206 G+P) (SN)	NECESSARY	80.00	80.00
1	IU BRACKET (SN)	NECESSARY	35.00	35.00
1	PANEL, FRONT:FIBREGLASS, FOR MB OC500 BUS (SN)	CRACKED	3,105.00	2,794.50
24	ADHESIVE:DIRECT GLAZING @\$37.00 (SN)	NECESSARY	888.00	888.00
1	ACTIVATOR (SN)	NECESSARY	80.00	80.00
			4,188.00	3,877.50
	<u>LABOUR</u>			
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		4,240.00	3,710.00
	TO PUTTY & RESPRAY.		942.00	772.00
	TOWING CHARGE.		200.00	200.00
			5,382.00	4,682.00
	GRAND TOTAL		17,850.55	16,011.99
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			13,750.00

Report Ref No. CS/LPC21010273/R1tf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.