

INCIDENT REPORT

1. Nature of Incident *(brief description or name of incident)*

Accident between Mo Guan - mini excavator and Public bus (Tower Transit Bus) – number SMB 82Z

2. Date & Time of Incident

28/09/2021 (Tuesday) around 1030am morning

3. Location of Incident *(provide map or sketch of incident site)*

Lim Chu Kang Road , Lp 246 – near Lim Chu Kang Lane 4.

(Please refer to the attached Photos Slides)

4. Details of Incident *(describe what and how it happens, who and what were involved)*

a) The mentioned work site was controlled by Portable Traffic Lights System.

b) Mo Guan had been working at the location for 3 weeks.

c) For StarHub Ltd.

d) On that day , Excavator Operator – Mr Soon Hock Theong was operating the excavator , he had dug up waste soil which had to be remove from site via loading onto the tipper lorry. He had to swing outwards in order to avoid the Bus Stop Shether. When he was carrying out that action , The mentioned Tower Transit Bus came along and the excavator boom with bucket hit onto the Bus Front right hand side. (refer to photo).

e) Mo Guan Site Supervisor – Mr Ramamoorthy Mutharasu was assisting with the site work for the day. (refer to photo)

f) No one was injured.

5. Effects of Incident *(describe its implications and impact on road users, e.g. lane closure spill into peak hours, cracks & settlement on roads, etc.)*

No traffic jam occurred.

6. Actions Taken *(describe who had responded to the incident and what actions were carried out).*

A-The Affected Bus was towed away around 1130am. (refer to photo)

B- I had re-briefed working teams on the way to control traffic by adding extra manpower to control.

Prepared by :

Andy Puah

General Manager

Mo Guan Construction Engineering Pte Ltd