

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010282/RPA3Q2**Date:** 24/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210017949
Claimant Vehicle No :	XE5968P	Insured Vehicle No :	SMY3055L
Date of Loss:	13/09/2021	Nature of Claim:	TP
		Claim No:	6043177299SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XE5968P		
Make & Model:	MERCEDES-BENZ AROCS, 7.7 D 2630 6X4 3900 ABS (A)	Engine No:	936912C0210734
Reg. Date:	20/11/2020 (Man. Year: 2020)	Chassis No:	W1T96401420463100
Colour:	Multi-colour	Odometer:	52202 km
Engine Capacity:	7698 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	315/80 R22.5	Rear Tyre Size:	315/80 R22.5 (D)
Front Left Side:	Firemax 8 mm	Rear Left Side:	Firemax 8/8 mm
Front Right Side:	Firemax 8 mm	Rear Right Side:	Firemax 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	662.06	662.06	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	468.00	400.00	68.00	14.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,130.06	1,062.06	68.00	6.02
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	05/10/2021		
Date Inspected:	08/10/2021	Inspected At:	Sembwaste Pte Ltd (HQ) Joo Koon Depot, 6 Joo Koon Road Singapore 629870
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*STEP PLATE	Deformed	587.92 FS	*587.92 FS
2	1		*ADD TURN SIGNAL LAMP	Cracked	74.14 FS	*74.14 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					662.06	662.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE ,REPAINT ,FRONT LEFT DAMAGE PARTS	New	468.00	400.00
Gross Labour Cost (\$\$)			468.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >