

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21010285/VPA3Q2**Date:** 09/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900099282
<b>Claimant Vehicle No :</b>	SBS6455H	<b>Insured Vehicle No :</b>	SML5760P
Date of Loss:	29/09/2021	Nature of Claim:	TP
		Claim No:	3278898293SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SBS6455H</b>		
Make & Model:	MERCEDES-BENZ CITARO O530, 6.4 L AT TURBO	Engine No:	902926C1032404
	ABS (A)		
Reg. Date:	01/07/2014 (Man. Year: 2013)	Chassis No:	WEB62808323125401
Colour:	Green	Odometer:	4903164 km
Engine Capacity:	6374 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	412.95	235.31	177.64	43.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,760.00	1,760.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,172.95</b>	<b>1,995.31</b>	<b>177.64</b>	<b>8.18</b>
<b>+ GST 7.00/7.00% (S\$)</b>	152.11	139.67	12.44	8.18
<b>Nett Amount (S\$)</b>	<b>2,325.06</b>	<b>2,134.98</b>	<b>190.08</b>	<b>8.18</b>
<b>+ Loss of Use (3.0 x S\$250.00/day) (S\$)</b>		750.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,886.98</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,880.00</b>		

INSPECTION

Date of Assignment:	05/10/2021		
Date Inspected:	06/10/2021	Inspected At:	LexBuild International Pte Ltd (HQ) 11 Tuas Bay Close, #04-02 West Star Singapore 636996
Estimated Period of Repair:	3.0 days		

**Adjuster:** Thevan Thomas Karthikesavan**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RHS INDICATOR LAMP (DISC 10%)	Cracked	111.45 F	*100.31 F
2	1		*RHS MARKER LAMP	Serviceable	145.20 F	*- F
3	2		*SCREW	Serviceable	6.30 F	*- F
4	1		*SG 3BUS STICKER (DISC 10%)	Necessary	150.00 F	*135.00 F
F=Franchise part.						
Total Parts (S\$)					412.95	235.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	SUPPLY SKILLED PAINTER & PAINT MATERIAL TO PUTTY ,GRINDING & SPRAYPAINT: REAR RHS WHEELARC PANEL,REAR RHS BODYPANEL	New	1,760.00	1,760.00
<b>Gross Labour Cost (\$)</b>			<b>1,760.00</b>	<b>1,760.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >