



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 7148G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,931.00	-
1	FRONT RH CORNER PANEL	TO REPAIR SEE LABOUR	735.00	-
1	FRONT RH SIGNAL LAMP	GRAZED	498.00	287.00
1	FRONT RH HEADLAMP	GRAZED	761.00	761.00
1	FRONT RH DOOR PANEL	DENTED	2,514.00	1,750.00
1	FRONT RH DOOR HINGE	NOT NECESSARY	182.00	-
1	FRONT RH DOOR CHECKER	NOT NECESSARY	88.00	-
1	FRONT RH WHEEL ARCH GARNISH	GRAZED	319.00	319.00
1	FRONT RH WING MIRROR	GRAZED	690.00	690.00
	LESS 15% DISCOUNT		-1,157.70	-571.05
			6,560.30	3,235.95
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIP (SN)	NOT NECESSARY	30.00	-
			30.00	-
	<u>LABOUR</u>			
	CHECK REAR WIRING AND LIGHTING SYSTEM.		70.00	30.00
	TRANSFER PARTS, ATTACHMENT FROM FRONT OLD DOOR TO NEW.		200.00	80.00
	PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT RH CORNER PANEL.		900.00	500.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,000.00	700.00
	APPLY ANTI RUST ON AFFECTED AREAS.		120.00	50.00
	REMOVE AND RENEW STICKER ON AFFECTED AREAS.		600.00	150.00
			2,890.00	1,510.00
	GRAND TOTAL		9,480.30	4,745.95



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,800.00
---	--	--	-----------------

Report Ref No. CS1/LAW21010286/Avf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.