

Your Ref: CF/LHP/jq/0688/20

Date: 18<sup>th</sup> Nov 2021

Our Ref: CS1/LAW21010286/Avf3e2

**M/s Tan Kok Quan Partnership**

1 Wallich Street #07-02

Guoco Tower

Singapore 078881

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: YP 7148G****INSURED VEHICLE: JKA 5066****ACCIDENT DATE: 01/10/2019**

We thank you for your instruction on 06/10/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of YP 7148G from M/s WG Appraisal Services.
- b) Final Repair Bill of YP 7148G from M/s Hiap Hong Motor Repair.
- c) Singapore Accident Statement of Vehicles YP 7148G.
- d) Police Report of Vehicles YP 7148G and JKA 5066
- e) Colour damaged vehicle photographs of YP 7148G.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

## 1. Information Recorded: -

Registration Number	: YP 7148G
Make & Model	: Isuzu FRR90SUQA-C
Chassis Number	: JALFRR907H7000129
Year of Registration	: 2017
Engine Capacity	: 5193 cc

- 2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.