

# WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647. Singapore 542224  
Email: winsongkk@hotmail.com Contact: 9747 0063  
Company Register No. 53326249J

Veron

## ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S : RICHLAND LOGISTICS SERVICES PTE LTD  
C/O HIAP HONG MOTOR REPAIR  
2 Kaki Bukit Avenue 2, #02-13  
Auto Hub Singapore 417921

Date : 24 December 2019  
Our Ref : WG/TP/2019-481

### REFERENCE PARTICULARS

Date of Accident : 01 October 2019  
Date of Inspection : 21 December 2019

Type of Inspection : Third Party Claim  
Date of Re-Inspn : Na

### VEHICLE PARTICULARS

Registration No : YP7148G  
Make : ISUZU  
Model : FRR90SUQA-C  
Year : 2017

Engine No : 4HK1598363  
Chassis No : JALFRR907H7000129  
Odometer : 136383km  
Colour : White

### CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good  
Foot Brake : Serviceable  
Hand Brake : Serviceable

General Body Work : Good  
Steering : Serviceable  
Lightings : Serviceable

### TYRE CONDITION (Remaining estimated life of tyre in mm)

	Make	Size
Front Near Side	Ohtsu	225/80R17.5
Front Off Side	Ohtsu	225/80R17.5
Rear Near Side	Ohtsu	225/80R17.5
Rear Off Side	Ohtsu	225/80R17.5

Thread Balance  
5mm  
5mm  
5mm  
5mm

### GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the front left portion.  
For details, refer to assessment for repairs and photographs attached.

### ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **S\$7,100.00** nett at lump sum basis. (Subject to GST if applicable)  
Under normal circumstances, estimated period required for repairs : Five ( 05 ) working days.

Enclosed Four ( 4 ) photographs depicting damage to the vehicle.

Inspection conducted at : HIAP HONG MOTOR REPAIR  
2 Kaki Bukit Avenue 2, #02-13. Auto Hub Singapore 417921

In accordance to your instruction, we have **not** authorise repairs and inspection was conducted strictly on a "**WITHOUT PREJUDICE BASIS**".

**Our Ref : WG/TP/2019-481**

**DESCRIPTION OF PARTS AND NATURE OF REPAIRS**

B) S/NE' T ITEM  
8 FRONT BUMPER CLIP

## NECESSARY

**Parts Total :**

C) LABOUR CHARGES & MISC  
9 CHECK REAR WIRING AND LIGHTNING SYSTEM  
10 TRANSFER PARTS, ATTACHMENT FROM FRONT OLD DOOR TO NEW  
11 PANEL BEATING ON AFFECTED AREAS  
12 SPRAY PAINTING ON AFFECTED AREAS  
13 APPLY ANTI RUST ON AFFECTED AREAS  
14 REMOVE AND RENEW STICKER ON AFFECTED AREAS

**Labour Total :**

\$	70.00	\$	<del>60.00</del>	30
\$	200.00	\$	180.00	20
\$	900.00	\$	<del>800.00</del>	500
\$	1,000.00	\$	900.00	700
\$	120.00	\$	100.00	50
\$	600.00	\$	<del>500.00</del>	150
\$	<u>2,890.00</u>	\$	<u>2,540.00</u>	

**Total Parts and Laboure :**

\$	9,480.30	\$	8,890.80
----	----------	----	----------

\$ 7,100.00

total: 4745.55  
1/5 3.8K  
04 Days.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date:

### POINT OF IMPACT

The impact was confined to the front right portion of the vehicle.  
The damages appeared to be consistent as per the accident report statement.  
Please refer the attached schedule and photographs for details.

### ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

### CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **\$7,100.00 nett** corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully  
WG APPRAISAL SERVICES

Winson Goh  
Automotive Appraiser

