

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21010288/AQCE2

Date: 25/02/2022

REFERENCE

Insured/Claimant:	YU QIAN	Policy No:	7210002173		
Date of Loss:	29/09/2021	Nature of Claim:	OD	Claim No:	0633860735SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX4006C		
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Engine No:	DEM027753
Reg. Date:	11/01/2021 (Man. Year: 2020)	Chassis No:	WAUZZZF56MA015362
Colour:	Blue	Odometer:	5259 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$180,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,156.00	13,898.32	7,257.68	34.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,552.00	4,022.00	4,530.00	52.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,708.00	17,920.32	11,787.68	39.68
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	28,908.00	17,120.32	11,787.68	40.78
+ GST 7.00/7.00% (S\$)	2,023.56	1,198.42	825.14	40.78
Nett Amount (S\$)	30,931.56	18,318.74	12,612.82	40.78

INSPECTION

Date of Assignment:	06/10/2021		
Date Inspected:	05/10/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,342.00 FS	*1,873.60 FS
2	2		*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE	Not Necessary	196.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Cracked	262.00 FS	*209.20 FS
5	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	63.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Cracked	262.00 FS	*209.20 FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	135.00 FS	*- FS
8	1		*FRONT BUMPER LOWER TRIM - LH	Not Necessary	48.00 FS	*- FS
9	1		*FRONT BUMPER LOWER TRIM - CENTER	Not Necessary	114.00 FS	*- FS
10	1		*RADIATOR GRILLE	Cracked	1,694.00 FS	*1,355.20 FS
11	1		*FOAM FILLER PIECE	Cracked	146.00 FS	*116.40 FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	845.00 FS	*- FS
13	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	36.00 FS	*- FS
14	1		*FRONT BUMPER TOP COVER	Not Necessary	127.00 FS	*- FS
15	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
16	1		*A/C STICKER	Not Necessary	8.00 FS	*- FS
17	1		*LOCK CARRIER TOP BRACKET	Cracked	137.00 FS	*109.60 FS
18	2		*LOCK CARRIER SUPPORT BRACKET - LH / RH	Not Necessary	58.00 FS	*- FS
19	1		*FRONT PARKING AID SENSOR - FRONT OUTER (NPA)	Not Necessary	0.00 FS	*- FS
20	1		*FRONT PARKING AID SENSOR - FRONT INNER (NPA)	Not Necessary	0.00 FS	*- FS
21	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
22	1		*HORN - LH	Not Necessary	126.00 FS	*- FS
23	1		*HORN BRACKET - LH	Not Necessary	29.00 FS	*- FS
24	1		*BONNET	Dented	3,312.00 FS	*2,649.60 FS
25	1		*BONNET ATTACHMENT PARTS	Not Necessary	123.00 FS	*- FS
26	1		*BONNET IMPACT PROTECTION - CENTER	Necessary	28.00 FS	*22.00 FS
27	2		*BONNET IMPACT PROTECTION - LH / RH	Necessary	56.00 FS	*43.68 FS
28	1		*BONNET STRIKER - LH	Not Necessary	50.00 FS	*- FS
29	1		*BONNET LID LOCK	Not Necessary	214.00 FS	*- FS
30	1		*BONNET LOCK COVER	Not Necessary	44.00 FS	*- FS
31	1		*FRONT FENDER - LH	Buckled	1,060.00 FS	*848.00 FS
32	1		*FRONT FENDER ATTACHMENT PARTS - LH	Not Necessary	53.00 FS	*- FS
33	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	74.00 FS	*- FS
34	1		*FRONT FENDER BRACKET - LH	Not Necessary	35.00 FS	*- FS
35	1		*FRONT FENDER BRACE - LH	Not Necessary	118.00 FS	*- FS
36	1		*FRONT FENDER FLEDGE COVER - LH LONG	Not Necessary	36.00 FS	*- FS
37	1		*FRONT FENDER FLEDGE COVER - LH SHORT	Not Necessary	16.00 FS	*- FS
38	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	275.00 FS	*- FS
39	1		*FRONT WHEEL SPOILER - LH	Torn	73.00 FS	*58.40 FS
40	1		*FRONT FENDER TRIM - LH	Necessary	164.00 FS	*130.80 FS
41	1		*LED HEADLIGHT - LH	Cracked	7,685.00 FS	*6,148.00 FS
42	1		*LIFT CYLINDER - LH	Not Necessary	198.00 FS	*- FS
43	1		*LIFT CYLINDER HOSE - LH (NPA)	Not Necessary	0.00 FS	*- FS
44	1		*RADIATOR AIR GUIDE - LH	Not Necessary	31.00 FS	*- FS
45	1		*RADIATOR AIR GUIDE - LH	Not Necessary	16.00 FS	*- FS
46	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	16.00 FS	*- FS
47	1		*FRONT DOOR CHROME TRIM - LH	Not Necessary	164.00 FS	*- FS
48	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
49	1		*SUNDRIES	Necessary	300.00 FS	*18.40 FS
50	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS - LH	Not Necessary	169.00 FS	*- FS
51	1		*HEADLIGHT COVER - LH (Supplementary)	Cracked	44.00 FS	*34.48 FS
52	1		*HEADLIGHT WASHER BRACKET - LH (Supplementary)	Cracked	15.00 FS	*11.76 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					21,156.00	13,898.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTSS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR	New	280.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,200.00	1,500.00
5	TO RESPRAY FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS FRONT DOOR	New	4,000.00	1,600.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			8,552.00	4,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >