

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21010289/Vvy3e2	
	8 SHENTON WAY SINGAPORE 0688		Date:	14/10/2021		
	ATTN: TEO KITTY			Code:	ASM	
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHD 3521C	Veh. Inspected	k	FBS 4439T	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S1M03J6T	Excess (\$)		0.00	
	Assign From	TEO KITTY	Assign Date		06/10/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA FZS	c.c		149	
	Engine No.	HIDDEN	Year of Reg.		2021	
	Chassis No.	ME1RG6627L0049453	Colour		RED	
	Odometer	7347 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	100/80-17	BRIDGESTONE		6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	140/60-17	BRIDGESTONE		6 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUS PORTION.	E VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND REAR RTION.				
5.	General Information					
	Accident Date	01/10/2021	Inspect Date /	Time	06/10/2021 ( 01:00 PM )	
	Survey held at	Survey held at M 1 MOTORING				
	411 CHANGI ROAD SINGAPORE 419860					
5a.	5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$3,500					
5b. Estimate Days of Repair						
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM21010289/Vvy3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

Tu

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser