



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKF 4985U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (CONSISTENT)	DEFORMED	783.00	783.00
1	REAR BUMPER SIDE HOLDER LH (CONSISTENT)	NOT NECESSARY	24.50	-
1	REAR BUMPER LOWER SPOILER (CONSISTENT)	TO REPAIR SEE LABOUR	523.00	-
	LESS 20% DISCOUNT		-	-156.60
			1,330.50	626.40
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	REAR LH WHEEL RIM (SN) (CONSISTENT)	NOT NECESSARY	750.00	-
			780.00	30.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER LOWER SPOILER.		400.00	300.00
	SPRAY PAINTING.		800.00	400.00
	TO REMOVE REVERSE SENSOR.		50.00	50.00
	TO PERFORM WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
			1,400.00	750.00
	GRAND TOTAL		3,510.50	1,406.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,100.00

Report Ref No. CS/ASM21010291/Auy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.